Profile/Photo Observation Report



Date: 03/29/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 297.4 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: Jen Costello PSR: P-103-020-021

Customer: Clean Date: 01/01/1900 Shape: C

Street: MISSOURI ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey:

US MH: M-103-021 DS MH: M-103-020 Total Length Surveyed (ft): 295.7

2.00 2800 16.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2800 16.00 Overall Rating: Overall Index: Overall Quick:

Downstream


	osition	Code	Observation	Video (sec)	Grade
103-021					
0.)	AMH	Manhole	10	NA
0. ///)	MWL	Water Level	21	NA
\\\ <u>.</u> 0)	DAGS(S01)	Deposits Attached Grease	32	M 2
\\	.1	TFA	Tap Factory Active	54	NA
\1!	5.0	DAGS(F01)	Deposits Attached Grease	86	M 2
10	04.2	MWL	Water Level	275	NA
/1:	13.9	DAGS(S02)	Deposits Attached Grease	306	M 2
//1:	15.3	TF	Tap Factory	321	NA
<u> </u>	21.0	TF	Tap Factory	346	NA
1	26.2	TF	Tap Factory	371	NA
12	26.8	DAGS(F02)	Deposits Attached Grease	384	M 2
1!	51.2	TF	Tap Factory	444	NA
2:	13.0	TF	Tap Factory	581	NA
/2:	18.7	DAGS(S03)	Deposits Attached Grease	604	M 2
/2:	19.1	TF	Tap Factory	617	NA
<u> /2</u> 2	25.8	TF	Tap Factory	643	NA
//23	30.7	DAGS(F03)	Deposits Attached Grease	664	M 2
1//20	95.7	AMH	Manhole	806	NA

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-103-021		

 AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000

Continuous Index:


Within 8" of Joint:

Remarks:

NO

Code: DAGS

Description: **Deposits Attached Grease**




Distance (ft): .0 Structural Grade: 0 O&M Grade: 2

Clock Start/From: 8 Clock To: 4

1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: **S01** Within 8" of Joint: NO



Description: Tap Factory Active

Distance (ft): 5.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 1

Clock To:

1st Value:

4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:




Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 15.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: NO



Code: MWL

Description: Water Level

Distance (ft): 104.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: DAGS

Description: Deposits Attached Grease


Distance (ft): 113.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

Value Percent: 5.000
Continuous Index: S02
Within 8" of Joint: NO

Remarks:

2nd Value:

Thursday, November 16, 2023



Description: Tap Factory


Distance (ft): 115.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**


Description: Tap Factory

Distance (ft): 121.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory

Distance (ft): 126.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 126.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:

Value Percent: 5.000
Continuous Index: F02
Within 8" of Joint: NO



Description: Tap Factory

Distance (ft): 151.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**


Description: Tap Factory

Distance (ft): 213.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 218.7
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:


1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S03
Within 8" of Joint: NO

Remarks:

Code: **TF**

Description: Tap Factory




Distance (ft): 219.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory

Distance (ft): 225.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: DAGS

Description: Deposits Attached Grease

4.000

Distance (ft): 230.7
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:

Value Percent: 5.000
Continuous Index: F03
Within 8" of Joint: NO



Code: AMH
Description: Manhole

Distance (ft): 295.7
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-103-020