Profile/Photo Observation Report



Date: 04/03/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 173.9 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: Jen Costello PSR: P-103-025-026

Customer: Clean Date: 01/01/1900 Shape: C

Street: W 39TH AVE Flow Control: Not Controlled
City: Hobart, IN Year Renewed:

Location:OtherTape/Media #:Purpose:Not KnownDia/Height:10"Use:SanitaryMaterial:PVC

Drain Area: NA Lining:

Category: NA

Comment:


Location Details: Direction of Survey: Downstream

US MH: M-103-025 DS MH: M-103-026 Total Length Surveyed (ft): 19.0

2.00 2300 6.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2300 6.00 Overall Index: Overall Rating: Overall Quick:

Position	Code	Observation	Video (sec)	Grade
103-025				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
3.5	DAGS(S01)	Deposits Attached Grease	39	M 2
19.0	DAGS(F01)	Deposits Attached Grease	82	M 2
19.0	MSA	Abandoned Survey	93	NA

Code:



Description:	Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-103-025	

 AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.0

Continuous Index:

Within 8" of Joint: NO

Remarks:

5.000

Code: DAGS

Description: Deposits Attached Grease



Distance (ft): 3.5
Structural Grade: 0
O&M Grade: 2

Clock To: 2

Clock To: 4

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: NO

Remarks:



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 19.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks:

Code: MSA

Description: Abandoned Survey



Distance (ft): 19.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: **DEBRIS UNDER WATER**