


## Profile/Photo Observation Report



|                   |                   |             |                        |            |                      |
|-------------------|-------------------|-------------|------------------------|------------|----------------------|
| Date:             | <b>03/26/2018</b> | Weather:    |                        | Coding:    | <b>PACP 6.0</b>      |
| Pipe Length (ft): | <b>156.7</b>      | Owner:      | <b>NA</b>              | Pre Clean: | <b>Not Known</b>     |
| P.O.#:            |                   | Surveyor:   | <b>Byrd Fitzgerald</b> | PSR:       | <b>P-103-028-029</b> |
| Customer:         |                   | Clean Date: | <b>01/01/1900</b>      | Shape:     | <b>C</b>             |

|                   |   |                             |                       |
|-------------------|---|-----------------------------|-----------------------|
| Street:           | <b>E 38th Ave</b>                             | Flow Control:               | <b>Not Controlled</b> |
| City:             | <b>Hobart, IN</b>                             | Year Renewed:               |                       |
| Location:         | <b>Other</b>                                  | Tape/Media #:               |                       |
| Purpose:          | <b>Not Known</b>                              | Dia/Height:                 | <b>12"</b>            |
| Use:              | <b>Sanitary</b>                               | Material:                   | <b>PVC</b>            |
| Drain Area:       | <b>NA</b>                                     | Lining:                     |                       |
| Category:         | <b>NA</b>                                     |                             |                       |
| Comment:          | <b>Debris, sediment. Solo will not deploy</b> |                             |                       |
| Location Details: |   | Direction of Survey:        | <b>Upstream</b>       |
| US MH:            | <b>M-103-028</b>                              | DS MH:                      | <b>M-103-029</b>      |
|                   |   | Total Length Surveyed (ft): | <b>5.4</b>            |

|                   |             |                   |             |                    |             |
|-------------------|-------------|-------------------|-------------|--------------------|-------------|
| O&M Index:        | <b>2.00</b> | O&M Quick:        | <b>2100</b> | O&M Rating:        | <b>2.00</b> |
| Structural Index: | <b>0.00</b> | Structural Quick: | <b>0000</b> | Structural Rating: | <b>0.00</b> |
| Overall Index:    | <b>2.00</b> | Overall Quick:    | <b>2100</b> | Overall Rating:    | <b>2.00</b> |


|  | Position | Code | Observation              | Video (sec) | Grade |
|--|----------|------|--------------------------|-------------|-------|
|  | .0       | AMH  | Manhole                  | 10          | NA    |
|  | .0       | MWL  | Water Level              | 21          | NA    |
|  | .0       | DAGS | Deposits Attached Grease | 32          | M 2   |
|  | 5.4      | MSA  | Abandoned Survey         | 54          | NA    |
|  |          |      |                          |             |       |



Code: **AMH**  
Description: **Manhole**  
  
Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks: **M-103-029**

---


|              |                    |
|--------------|--------------------|
| Code:        | <b>MWL</b>         |
| Description: | <b>Water Level</b> |



|                     |               |
|---------------------|---------------|
| Distance (ft):      | <b>.0</b>     |
| Structural Grade:   | <b>0</b>      |
| O&M Grade:          | <b>0</b>      |
| Clock Start/From:   |               |
| Clock To:           |               |
| 1st Value:          |               |
| 2nd Value:          |               |
| Value Percent:      | <b>50.000</b> |
| Continuous Index:   |               |
| Within 8" of Joint: | <b>NO</b>     |
| Remarks:            |               |


---

|              |                                 |
|--------------|---------------------------------|
| Code:        | <b>DAGS</b>                     |
| Description: | <b>Deposits Attached Grease</b> |



|                     |               |
|---------------------|---------------|
| Distance (ft):      | <b>.0</b>     |
| Structural Grade:   | <b>0</b>      |
| O&M Grade:          | <b>2</b>      |
| Clock Start/From:   | <b>9</b>      |
| Clock To:           | <b>3</b>      |
| 1st Value:          |               |
| 2nd Value:          |               |
| Value Percent:      | <b>10.000</b> |
| Continuous Index:   |               |
| Within 8" of Joint: | <b>NO</b>     |
| Remarks:            |               |

---



|                     |                         |
|---------------------|-------------------------|
| Code:               | <b>MSA</b>              |
| Description:        | <b>Abandoned Survey</b> |
| Distance (ft):      | <b>5.4</b>              |
| Structural Grade:   | <b>0</b>                |
| O&M Grade:          | <b>0</b>                |
| Clock Start/From:   |                         |
| Clock To:           |                         |
| 1st Value:          |                         |
| 2nd Value:          |                         |
| Value Percent:      |                         |
| Continuous Index:   |                         |
| Within 8" of Joint: | <b>NO</b>               |
| Remarks:            | <b>stuck on wall</b>    |