Profile/Photo Observation Report

Customer:

Location:



Date: 03/23/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 155.0 Owner: NA Pre Clean: Not Known

P.O.#: Surveyor: Jen Costello PSR: P-103-033-LS005

01/01/1900

Tape/Media #:

Shape:

Street: E 38th Ave Flow Control: Not Controlled

Clean Date:

City: Hobart, IN Year Renewed:

Purpose: Not Known Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Other

Comment:


Location Details: Direction of Survey: Downstream

US MH: M-103-033 DS MH: M-103-033 Total Length Surveyed (ft): 15.0

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:


Positio	n Code	Observation	Video (sec)	Grade
M-103-033				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
15.0	MSA	Abandoned Survey	62	NA
Camera Direction M(103)033				

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-103-033

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

20.000

NO

Code: MSA

Description: **Abandoned Survey**



Distance (ft): 15.0 Structural Grade: 0

O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: Within 8" of Joint:

Remarks: overturned

NO