
Profile/Ph	oto Observatio	n Report				RedZone
Date:	03/22/2018	Weather:	NA		0	PACP 6.0
Pipe Length (ft P.O.#:	): <b>64.2</b>	Owner:	NA Selasie Honu	Pre		Not Known 2-103-119-118
Customer:		Surveyor: Clean Date:		-	аре: <b>С</b>	
Street:	W 38TH AVE & MISSOURI		Flow Control:	Not	Controlled	
City:	Hobart, IN		Year Renewed			
Location:	Other		Tape/Media #:			
Purpose:	Not Known		Dia/Height:	8"		
Use:	Sanitary		Material:	PVC		
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detail	ls:		Direction of Su	rvey: Dov	wnstream	
US MH:	M-103-118	DS MH:	M-103-119	Total Length S	urveyed (ft):	66.5
0&M Index:	0.00	O&M Quick:	00	000 O&M I	Rating:	0.00
itructural Index:	0.00	Structural Q			ural Rating:	0.00
Overall Index:	0.00	Overall Quic	k: 00	000 Overal	Il Rating:	0.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-103-118



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 5.000 Continuous Index: Within 8" of Joint: NO Remarks:



Code: Description:	AMH Manhole
Distance (ft):	66.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-103-119