Profile/Photo Observation Report

Customer:



Date: 03/23/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 219.8 Owner: NA Pre Clean: Not Known

P.O.#: Surveyor: **Justin Gonzales** PSR: **P-103-121-120**

01/01/1900

Shape:

Street: MISSOURI ST Flow Control: Not Controlled

Clean Date:

City: Hobart, IN Year Renewed:

Location:OtherTape/Media #:Purpose:Not KnownDia/Height:8"Use:SanitaryMaterial:PVC

Use: Sanitary Material:
Drain Area: NA Lining:

Category: NA


Comment: possibly buried or paved over
Location Details: Direction of Survey: Downstream

US MH: M-103-120 DS MH: M-103-121 Total Length Surveyed (ft): 217.4

2.00 2H00 90.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2H00 90.00 Overall Rating: Overall Index: Overall Quick:


Position	Code	Observation	Video (sec)	Grade
103-120				
.0	АМН	Manhole	10	NA
.0	MWL	Water Level	21	NA
\0	DAZ(S01)	Deposits Attached Other	32	M 2
48.5	TF	Tap Factory	141	NA
/105.9	TF	Tap Factory	267	NA
111.7	TF	Tap Factory	291	NA
122.3	TF	Tap Factory	325	NA
129.5	TF	Tap Factory	352	NA
146.9	TF	Tap Factory	399	NA
183.9 199.3 199.7	TF	Tap Factory	484	NA
	TF	Tap Factory	528	NA
	DSC	Deposits Settled Compacted	541	M 2
207.0	TF	Tap Factory	568	NA
215.8	DSC	Deposits Settled Compacted	597	M 2
217.4 217.4	MSA	Abandoned Survey	611	NA
	DAZ(F01)	Deposits Attached Other	622	M 2

Code:



	7		
Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-103-120		

 AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:


Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

5.000




Code: DAZ

Description: **Deposits Attached Other**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 7 Clock To: 5 1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: **S01** Within 8" of Joint: YES Remarks: WANDER



Description: Tap Factory


Distance (ft): 48.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**


Description: Tap Factory

Distance (ft): 105.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory

Distance (ft): 111.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 122.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory

Distance (ft): 129.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**


Description: Tap Factory

Distance (ft): 146.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory

Distance (ft): 183.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**


Description: Tap Factory

Distance (ft): 199.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: DSC

Description: Deposits Settled Compacted

Distance (ft): 199.7
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 6

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

NO

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 207.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: DSC

Description: Deposits Settled Compacted

Distance (ft): 215.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 5
Clock To: 7

1st Value: 2nd Value:


Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 217.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: CANNOT PASS DSC



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 217.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks: WANDER