Profile/Photo Observation Report



Date: 03/22/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 158.4 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: Surveyor: Selasie Honu P-103-122-116

Customer: Clean Date: 01/01/1900 Shape:

W 38TH AVE Flow Control: **Not Controlled** Street:

City: Hobart, IN Year Renewed: Other Tape/Media #: Location:

Purpose: **Not Known** Dia/Height: 8" **PVC** Use: Sanitary Material:

NΑ Drain Area: Lining:

NA Comment: CNL, buried possibly

Category:

Location Details: Direction of Survey: **Downstream**

US MH: M-103-122 Total Length Surveyed (ft): DS MH: M-103-116 152.9

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:


Position	Code	Observation	Video (sec)	Grade
103-122				
0.	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
60.1	TF	Tap Factory	153	NA
125.2	MWL	Water Level	295	NA
152.9	AMH	Manhole	362	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-103-122

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:


Within 8" of Joint: NO

Remarks:

Code:

TF

Description: Tap Factory



Distance (ft): 60.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 10

Clock To:

Remarks:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: MWL

Description: Water Level

Distance (ft): 125.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 30.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: AMH
Description: Manhole

Distance (ft): 152.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-103-116