

## Profile/Photo Observation Report





Date:	10/17/2021	Weather:		Coding:	PACP 6.0
Pipe Length (ft):		Owner:	Hobart, IN	Pre Clean:	Not Known
P.O.#:	849_1	Surveyor:	M. Pielacha	PSR:	P-105-001-002
Customer:	Hobart, IN	Clean Date:		Shape:	C

Street:	East Home Avenue	Flow Control:	
City:	Hobart, IN	Year Renewed:	
Location:	Woods	Tape/Media #:	849
Purpose:	Routine Assessment	Dia/Height:	8"
Use:	Sanitary	Material:	PVC
Drain Area:		Lining:	
Category:	NA		
Comment:			

Location Details:		Direction of Survey:	Upstream
US MH:	M-105-1	DS MH:	M-105-2
		Total Length Surveyed (ft):	40.9

O&M Index:	4.00	O&M Quick:	4200	O&M Rating:	8.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	4.00	Overall Quick:	4200	Overall Rating:	8.00

	Position	Code	Observation	Video (sec)	Grade
	.0	AMH	Manhole	0	NA
	.0	MWL	Water Level	18	NA
	29.3	MWL	Water Level	79	NA
	31.4	MCU(S01)	Camera Underwater	98	M 4
	40.9	MGO	General Observation	216	NA
	40.9	MSA	Abandoned Survey	229	NA
	40.9	MCU(F01)	Camera Underwater	239	M 4



Code: **AMH**  
 Description: **Manhole**

Distance (ft): **.0**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **M-105-2**




Code:	<b>MWL</b>
Description:	<b>Water Level</b>
Distance (ft):	<b>.0</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>0</b>
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	<b>5.000</b>
Continuous Index:	
Within 8" of Joint:	<b>NO</b>
Remarks:	

---



Code:	<b>MWL</b>
Description:	<b>Water Level</b>
Distance (ft):	<b>29.3</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>0</b>
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	<b>35.000</b>
Continuous Index:	
Within 8" of Joint:	<b>NO</b>
Remarks:	


---



Code: **MCU**  
Description: **Camera Underwater**

Distance (ft): **31.4**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **S01**  
Within 8" of Joint: **NO**  
Remarks:


---



Code: **MGO**  
Description: **General Observation**

Distance (ft): **40.9**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks: **Under water debris**


---



Code: **MSA**  
Description: **Abandoned Survey**

Distance (ft): **40.9**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks: **Under water debris**

---



Code: **MCU**  
Description: **Camera Underwater**

Distance (ft): **40.9**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **F01**  
Within 8" of Joint: **NO**  
Remarks: