## **Profile/Photo Observation Report**



Date: 03/24/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 203.5 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: Surveyor: JUSTIN GONZALES PSR: P-108-005-006

Customer: Clean Date: 01/01/1900 Shape: C

Street: 14TH LN Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Downstream** 

US MH: M-108-006 DS MH: M-108-005 Total Length Surveyed (ft): 200.9

2.00 2G00 84.00 O&M Index: O&M Quick: O&M Rating: 1.00 1100 1.00 Structural Quick: Structural Rating: Structural Index: 1.98 2G11 85.00 Overall Rating: Overall Index: Overall Quick:

Position	Code	Observation	Video (sec)	Grade
108-006				
0.	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
0.	DAGS(S01)	Deposits Attached Grease	32	M 2
26.1	JOM	Joint Offset Medium	96	S 1
26.1	RPR	Repair Point Pipe Replaced	107	NA
27.9	TF	Tap Factory	123	NA
\31.7	RPR	Repair Point Pipe Replaced	143	NA
79.9	TFD	Tap Factory Defective	251	M 2
/129.7	MGO	General Observation	362	NA
136.1	TF	Tap Factory	387	NA
174.3	TFD	Tap Factory Defective	476	M 2
200.9	AMH	Manhole	541	NA
200.9	DAGS(F01)	Deposits Attached Grease	553	M 2

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-108-006		

 $\mathsf{AMH}$ 



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO

terrarits.

Code: DAGS

Description: Deposits Attached Grease



Distance (ft): .0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: YES
Remarks: WANDER



Code: **JOM** 

Description: Joint Offset Medium

Distance (ft): 26.1
Structural Grade: 1
O&M Grade: 0

Clock Start/From: Clock To:

1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

NO



Description: Repair Point Pipe Replaced



Distance (ft): 26.1
Structural Grade: 0


O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: VCP TO PVC



Code: **TF** 

Description: Tap Factory


Distance (ft): 27.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **6.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: RPR

Description: Repair Point Pipe Replaced

Distance (ft): 31.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: **PVC TO VCP; PVC END** 



Code: **TFD** 

Description: Tap Factory Defective

Distance (ft): 79.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 9

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: **DEPOSITS BLOCKING MOUTH OF TAP** 



Code: MGO


Description: General Observation

Distance (ft): 129.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: TOILET TISSUE



Code: TF

Description: **Tap Factory** 

Distance (ft): 136.1 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 9


Clock To:

1st Value:

4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Description: **Tap Factory Defective** 



Distance (ft): 174.3 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 3

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

**DEPOSITS BLOCKING MOUTH OF TAP** Remarks:



Code: AMH
Description: Manhole

Distance (ft): 200.9
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-108-005



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 200.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:

2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:
YES

Remarks: WANDER