Profile/Ph	oto Observation	Report				RedZon
Date:	03/24/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft	): <b>203.5</b>	Owner:	NA		Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	JUSTIN GON	ZALES	PSR:	P-108-005-006
Customer:		Clean Date:	01/01/1900		Shape:	С
Street:	FOXCROFT STREET		Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renewed	d:		
Location:	Light Highway		Tape/Media #	<b>!:</b>		
Purpose:	Routine Assessment	t	Dia/Height:		12"	
Use:	Sanitary		Material:		VCP	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detail	ls:		Direction of S	urvey:	Downstream	
US MH:	M-108-006	DS MH:	M-108-005	Т	otal Length Surveyed (ft)	200 <b>.</b> 9
0&M Index:	2.00	O&M Quick:	2	G00	O&M Rating:	84.00
Structural Index:	1.00	 Structural Qu	ick: 1	100	Structural Rating:	1.00
Overall Index:	1.98	Overall Quick	: 2	G11	Overall Rating:	85.00

		Position	Code	Observation	Video (sec)	Grade
M-108-006						
	$ \longrightarrow $	.0	AMH	Manhole	10	NA
		.0	MWL	Water Level	21	NA
		\ <u>.</u> 0	DAGS(S01)	Deposits Attached Grease	32	M 2
		26.1	JOM	Joint Offset Medium	96	S 1
		26.1	RPR	Repair Point Pipe Replaced	107	NA
		27.9	TF	Tap Factory	123	NA
		31.7	RPR	Repair Point Pipe Replaced	143	NA
		79.9	TFD	Tap Factory Defective	251	M 2
		/ 129.7	MGO	General Observation	362	NA
5	/	136.1	TF	Tap Factory	387	NA
ecti		174.3	TFD	Tap Factory Defective	476	M 2
a Dir		200.9	AMH	Manhole	541	NA
Camera Direction		200.9	DAGS(F01)	Deposits Attached Grease	553	M 2
		)5				
INI-	108-00	12				



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-108-006



Code: Description:

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 5.000 Continuous Index: Within 8" of Joint: NO Remarks:

MWL

Water Level

Code:	DAGS
Description:	Deposits Attached Grease

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	S01
Within 8" of Joint:	YES
Remarks:	WANDER




Code:JOMDescription:Joint Offset Medium

Distance (ft):	26.1
Structural Grade:	1
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	RPR
Description:	Repair Point Pipe Replaced
Distance (ft):	26.1


Distance (rej.	2011
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	VCP TO PVC



Code:	TF
Description:	Tap Factory


Distance (ft):	27.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	

Remarks:



Code: Description:	RPR Repair Point Pipe Replaced
Distance (ft):	31.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO


PVC TO VCP; PVC END



Code:TFDDescription:Tap Factory Defective


Distance (ft): 79.9 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 9 Clock To: 1st Value: 4.000 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:

DEPOSITS BLOCKING MOUTH OF TAP



Code:	MGO
Description:	General Observation
Distance (ft):	129.7
Structural Grade:	0

Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	TOILET TISSUE



Code:	TF
Description:	Tap Factory

Distance (ft):	136.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



TFD
Tap Factory Defective
174.3
0
2
3
4.000
DEPOSITS BLOCKING MOUTH OF TAP



Code: AMH Description: Manhole

Distance (ft):200.9Structural Grade:0O&M Grade:0Clock Start/From:0Clock To:11st Value:22nd Value:4Value Percent:4Continuous Index:NORemarks:M-108

M-108-005

Code: Description: DAGS Deposits Attached Grease



Distance (ft):	200.9
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	F01
Within 8" of Joint:	YES
Remarks:	WANDER