## **Profile/Photo Observation Report**



Date: 03/24/2018 Weather: **PACP 6.0** Coding:

Pipe Length (ft): 171.4 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: **Justin Gonzales** PSR: P-108-017-027

Customer: 01/01/1900 Clean Date: Shape:

14TH LN & ALABMA ST Flow Control: **Not Controlled** Street:

Surveyor:

City: Hobart, IN Year Renewed: Tape/Media #: Location: **Light Highway** 

Purpose: **Routine Assessment** Dia/Height: 12" Use: Sanitary Material: **VCP** 

NA Drain Area: Lining:

Category: NA Comment: R\_M at 161 ft debris .Flow direction wrong

**Location Details:** Direction of Survey: **Downstream** 

US MH: M-108-027 DS MH: M-108-017 Total Length Surveyed (ft): 163.2

1.51 **2E1E** 98.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 1.51 **2E1E** 98.00 Overall Index: Overall Quick: Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
108-	027				
	0.	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	<u>.0</u>	DAGS(S01)	Deposits Attached Grease	32	M 2
	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	RFJ	Roots Fine Joint	49	M 1
	7.3	RFJ(S02)	Roots Fine Joint	69	M 1
	38.5	TF	Tap Factory	143	NA
	40.9	TF	Tap Factory	160	NA
	136.8	MGO	General Observation	363	NA
	163.2	MSA	Abandoned Survey	428	NA
	163.2	RFJ(F02)	Roots Fine Joint	439	M 1
	163.2	DAGS(F01)	Deposits Attached Grease	450	M 2

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-108-027		

**AMH** 



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO

Code: DAGS

Description: Deposits Attached Grease



Distance (ft): .0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: YES
Remarks: WANDER



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 2.5
Structural Grade: 0

O&M Grade: 1

Clock Start/From: 7


Clock To: 9

1st Value: 2nd Value: Value Percent:

Continuous Index: Within 8" of Joint:

Remarks:

YES



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 7.3
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 7
Clock To: 5
1st Value:
2nd Value:
Value Percent:
Continuous Index: 502

Within 8" of Joint:

Remarks: WANDER

YES



Code: **TF** 

Description: Tap Factory

4.000

Distance (ft): 38.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Code: **TF** 

Description: Tap Factory



Distance (ft): 40.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MGO

Description: General Observation

Distance (ft): 136.8
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: TOILET TISSUE; UNKNOWN DEPOSIT



Code: MSA

Description: Abandoned Survey

Distance (ft): 163.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: ROBOT TURNED OVER



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 163.2
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value: Value Percent:

Continuous Index: F02
Within 8" of Joint: YES

Remarks: WANDER



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 163.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:

2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:
YES

Remarks: WANDER