Profile/Photo Observation Report



Profile/Photo Observation Report								
Date: Pipe Length (ft P.O.#: Customer:	989_1	Weather: Owner: Surveyor: Clean Date:	Hobart, M. Piela		Pre Clean: PSR:	PACP 6.0 Not Known P-108-030-029 C		
	Hobart, IN	Clean Date.			Shape:			
Street:	Off Mississippi Lane		Flow Con					
City:	Hobart, IN		Year Rene	ewed:				
Location:	Yard		Tape/Me	dia #:	989			
Purpose:	Routine Assessment		Dia/Heigh	nt:	10"			
Use:	Sanitary		Material:		VCP			
Drain Area:			Lining:					
Category:	NA							
Comment:								
Location Detail	s:		Direction	of Survey:	Upstream			
US MH:	M-108-29	DS MH:	M-108-30		Total Length Surveyed (ft):	217.4		
O&M Index:	1.57	O&M Quick:		3122	O&M Rating:	11.00		
Structural Index:	2.00	Structural Qu		2200	Structural Rating:	4.00		
Overall Index:	1.67	Overall Quicl		3124	Overall Rating:	15.00		
								

Thursday, May 4, 2023

	Position	Code	Observation	Video (sec)	Grade
(-108 -3	0				
	.0	AMH	Manhole	0	NA
	0.	MWL	Water Level	38	NA
/	\\3.0	RFJ	Roots Fine Joint	94	M 1
	\13.1	RFJ	Roots Fine Joint	157	M 1
	21.5	TFD	Tap Factory Defective	197	M 2
ш	21.5	RFL	Roots Fine Lateral	208	M 1
ш	71.8	RFJ	Roots Fine Joint	293	M 1
	83.6	TFA	Tap Factory Active	325	NA
	84.9	TF	Tap Factory	344	NA
	145.5	TF	Tap Factory	438	NA
ш	147.7	TF	Tap Factory	458	NA
ш	173.2	CL	Crack Longitudinal	508	S 2
	173.2	CL	Crack Longitudinal	520	S 2
	194.0	RMJ	Roots Medium Joint	561	M 3
	214.4	TFD	Tap Factory Defective	603	M 2
	216.4	TF	Tap Factory	626	NA
	217.4	MSA	Abandoned Survey	755	NA



Code:	AMH
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-108-30



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

....



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 3.0
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 7
Clock To:
1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 13.1
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 4

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 21.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: roots



Code: RFL

Description: Roots Fine Lateral

Distance (ft): 21.5
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 4

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 71.8
Structural Grade: 0

O&M Grade: 1

Clock Start/From: 9

Clock To:

1st Value:

Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:

2nd Value:



Code: TFA

Description: Tap Factory Active

Distance (ft): 83.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF**

Description: Tap Factory

Distance (ft): 84.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 10


Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: TF

Description: **Tap Factory**

Distance (ft): 145.5 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 3

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: TF

Description: **Tap Factory**

Distance (ft): 147.7 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 9

Clock To:

4.000 1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:

7 Thursday, May 4, 2023



Code: CL

Description: Crack Longitudinal

Distance (ft): 173.2
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 12

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: CL

Description: Crack Longitudinal

Distance (ft): 173.2
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 6

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 194.0
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 214.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: roots



Code: **TF**

Description: Tap Factory

Distance (ft): 216.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:


1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 217.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: large roots