

Profile/Photo Observation Report




Date:	03/24/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft):	115.6	Owner:	NA	Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	Byrd Fitzgerald	PSR:	P-108-035-046
Customer:		Clean Date:	01/01/1900	Shape:	C

Street:	FOXCROFT STREET	Flow Control:	Not Controlled
City:	Hobart, IN	Year Renewed:	
Location:	Light Highway	Tape/Media #:	
Purpose:	Routine Assessment	Dia/Height:	12"
Use:	Sanitary	Material:	VCP
Drain Area:	NA	Lining:	
Category:	NA		
Comment:	Flow direction wrong		

Location Details:		Direction of Survey:	Upstream
US MH:	M-108-046	DS MH:	M-108-035
		Total Length Surveyed (ft):	103.2

O&M Index:	2.00	O&M Quick:	3123	O&M Rating:	10.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	3123	Overall Rating:	10.00

	Position	Code	Observation	Video (sec)	Grade
					
	.0	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	12.3	RPL(S01)	Repair Localized Liner	58	NA
	15.6	RPL(F01)	Repair Localized Liner	77	NA
	18.9	RPL(S02)	Repair Localized Liner	96	NA
	22.9	RPL(F02)	Repair Localized Liner	115	NA
	27.0	RPL(S03)	Repair Localized Liner	135	NA
	31.1	RPL(F03)	Repair Localized Liner	155	NA
	35.3	RPL(S04)	Repair Localized Liner	175	NA
	39.5	RPL(F04)	Repair Localized Liner	195	NA
	43.7	RPL(S05)	Repair Localized Liner	217	NA
	46.1	DSZ	Deposits Settled Other	234	M 2
	47.8	RPL(F05)	Repair Localized Liner	249	NA
	61.0	RMJ	Roots Medium Joint	288	M 3
	61.0	LD	Alignment Down	300	M 1
	62.7	TFD	Tap Factory Defective	316	M 2
	64.3	TFD	Tap Factory Defective	333	M 2
	103.2	AMH	Manhole	424	NA

Code: **AMH**
Description: **Manhole**



Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks: **M-108-035**

Code:	MWL
Description:	Water Level



Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	

Code:	RPL
Description:	Repair Localized Liner



Distance (ft):	12.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	S01
Within 8" of Joint:	NO
Remarks:	lining

Code: **RPL**
Description: **Repair Localized Liner**




Distance (ft): **15.6**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From: **7**
Clock To: **5**
1st Value:
2nd Value:
Value Percent:
Continuous Index: **F01**
Within 8" of Joint: **NO**
Remarks: **lining**

Code: **RPL**
Description: **Repair Localized Liner**




Distance (ft): **18.9**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From: **7**
Clock To: **5**
1st Value:
2nd Value:
Value Percent:
Continuous Index: **S02**
Within 8" of Joint: **NO**
Remarks: **lining**

Code: **RPL**
Description: **Repair Localized Liner**




Distance (ft): **22.9**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From: **7**
Clock To: **5**
1st Value:
2nd Value:
Value Percent:
Continuous Index: **F02**
Within 8" of Joint: **NO**
Remarks: **lining**

Code: **RPL**
Description: **Repair Localized Liner**



Distance (ft): **27.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From: **7**
Clock To: **5**
1st Value:
2nd Value:
Value Percent:
Continuous Index: **S03**
Within 8" of Joint: **NO**
Remarks: **lining**

Code: **RPL**
Description: **Repair Localized Liner**




Distance (ft): **31.1**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From: **7**
Clock To: **5**
1st Value:
2nd Value:
Value Percent:
Continuous Index: **F03**
Within 8" of Joint: **NO**
Remarks: **lining**

Code: **RPL**
Description: **Repair Localized Liner**



Distance (ft): **35.3**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From: **7**
Clock To: **5**
1st Value:
2nd Value:
Value Percent:
Continuous Index: **S04**
Within 8" of Joint: **NO**
Remarks: **lining**

Code: **RPL**
Description: **Repair Localized Liner**



Distance (ft): **39.5**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From: **7**
Clock To: **5**
1st Value:
2nd Value:
Value Percent:
Continuous Index: **F04**
Within 8" of Joint: **NO**
Remarks: **lining**

Code: **RPL**
Description: **Repair Localized Liner**



Distance (ft): **43.7**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From: **7**
Clock To: **5**
1st Value:
2nd Value:
Value Percent:
Continuous Index: **S05**
Within 8" of Joint: **NO**
Remarks: **lining**

Code: **DSZ**
Description: **Deposits Settled Other**



Distance (ft): **46.1**
Structural Grade: **0**
O&M Grade: **2**
Clock Start/From: **6**
Clock To:
1st Value:
2nd Value:
Value Percent: **5.000**
Continuous Index:
Within 8" of Joint: **NO**
Remarks: **tissue**

Code: **RPL**
Description: **Repair Localized Liner**




Distance (ft): **47.8**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From: **7**
Clock To: **5**
1st Value:
2nd Value:
Value Percent:
Continuous Index: **F05**
Within 8" of Joint: **NO**
Remarks: **lining**

Code: **RMJ**
Description: **Roots Medium Joint**




Distance (ft): **61.0**
Structural Grade: **0**
O&M Grade: **3**
Clock Start/From: **7**
Clock To: **5**
1st Value:
2nd Value:
Value Percent: **10.000**
Continuous Index:
Within 8" of Joint: **YES**
Remarks:

Code: **LD**
Description: **Alignment Down**



Distance (ft): **61.0**
Structural Grade: **0**
O&M Grade: **1**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **5.000**
Continuous Index:
Within 8" of Joint: **NO**
Remarks:

Code: **TFD**
Description: **Tap Factory Defective**



Distance (ft): **62.7**
Structural Grade: **0**
O&M Grade: **2**
Clock Start/From: **10**
Clock To:
1st Value: **4.000**
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks: **blocked by roots**

Code: **TFD**
Description: **Tap Factory Defective**



Distance (ft): **64.3**
Structural Grade: **0**
O&M Grade: **2**
Clock Start/From: **2**
Clock To:
1st Value: **4.000**
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks: **blocked by roots**



Code:	AMH
Description:	Manhole
Distance (ft):	103.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-108-046