## **Profile/Photo Observation Report**



Date: 03/25/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 275.3 Owner: NA Pre Clean: Not Known

P.O.#: Surveyor: **Byrd Fitzgerald** PSR: **P-203-045-043** 

Customer: Clean Date: 01/01/1900 Shape: C

Street: ALLEY BETWEEN MAITLAND ST & EV Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: PVC

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Upstream


US MH: M-203-043 DS MH: M-203-045 Total Length Surveyed (ft): 7.9

4.00 4.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 4.00 4.00 Overall Index: Overall Quick: Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
M(203-)0	45				
	.0	MCU	Camera Underwater	10	M 4
	.0	AMH	Manhole	21	NA
	\.0	MWL	Water Level	32	NA
	7.9	MSA	Abandoned Survey	59	NA
Camera Direction					
M(203 <del>)</del> 0	43				

Code:

Description:



Distance (ft):

Structural Grade:

O&M Grade:

Clock Start/From:

Clock To:

1st Value:

2nd Value:

Value Percent:

Continuous Index:


Within 8" of Joint:

NO

Remarks:

MCU

**Camera Underwater** 



Code: AMH
Description: Manhole

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-203-045



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:
Clock To:
1st Value:

Value Percent: 100.000

Continuous Index:

2nd Value:

Within 8" of Joint: NO Remarks: mcu



Code: MSA

Description: Abandoned Survey

Distance (ft): 7.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO Remarks: mcu