## **Profile/Photo Observation Report**



Date: 03/25/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 139.8 Owner: NA Pre Clean: **Not Known** P.O.#: **Byrd Fitzgerald** PSR: P-203-046-045 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: E 38th Ave Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:


Location Details: Direction of Survey: **Downstream** 

US MH: M-203-045 DS MH: M-203-046 Total Length Surveyed (ft): 6.6

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:


Position	Code	Observation	Video (sec)	Grade
M-203-045				
.0	АМН	Manhole	10	NA
0.	MWL	Water Level	21	NA
6.6	MSA	Abandoned Survey	46	NA
Camera Direction				

Code:



Description:	Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-203-045	

**AMH** 



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO



Code: MSA

Description: **Abandoned Survey** 

Distance (ft): 6.6 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

NO Remarks: camera stopped/no blockage