## **Profile/Photo Observation Report**



Date: 03/24/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 232.8 Owner: NA Pre Clean: **Not Known** P.O.#: **Justin Gonzales** PSR: Surveyor: P-203-058-056

Customer: Clean Date: 01/01/1900 Shape: C

Street: E 38th Ave Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: PVC

Drain Area: NA Lining: Category: NA

Comment: Graveled over

Location Details: Direction of Survey: **Downstream** 


US MH: M-203-056 DS MH: M-203-058 Total Length Surveyed (ft): 126.1

2.00 2D00 50.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2D00 50.00 Overall Index: Overall Quick: Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
203-	056				
	0.	AMH	Manhole	10	NA
ш	0.	MWL	Water Level	21	NA
ш	0.	DAGS(S01)	Deposits Attached Grease	32	M 2
ш	4.1	TF	Tap Factory	53	NA
Ш	26.3	TF	Tap Factory	109	NA
ш	68.5	TF	Tap Factory	206	NA
ш	90.5	TF	Tap Factory	261	NA
ш	126.1	MSA	Abandoned Survey	343	NA
ш	126.1	DAGS(F01)	Deposits Attached Grease	355	M 2
	11				

Code:


Description:



Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-203-056

AMH

Manhole



Code: MWL

Description: **Water Level** 

Distance (ft): .0 0 Structural Grade: O&M Grade: 0 Clock Start/From:

Clock To: 1st Value:

2nd Value:

Value Percent: 10.000


Continuous Index:

Within 8" of Joint:

Remarks:


NO


Code: **DAGS** Description: **Deposits Attached Grease** 



2nd Value:

Value Percent: 5.000 Continuous Index: **S01** Within 8" of Joint: YES Remarks: WANDER





Code: **TF** 

Description: Tap Factory


Distance (ft): 4.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 26.3
Structural Grade: 0

O&M Grade: 0


Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 68.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 90.5
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 9

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 126.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: ROBOT HAS STOPPED



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 126.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

2nd Value:

Remarks: WANDER