Profile/Photo Observation Report



Date: 03/23/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 271.6 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: **Justin Gonzales** PSR: P-203-065-060

Customer: Clean Date: 01/01/1900 Shape: C

Street: W 38TH AVE Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 12"
Use: Sanitary Material: PVC

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-203-065 DS MH: M-203-060 Total Length Surveyed (ft): 251.6

2.00 2100 104.00 O&M Index: O&M Quick: O&M Rating: 2.00 2100 2.00 Structural Quick: Structural Rating: Structural Index: 2.00 2100 106.00 Overall Rating: Overall Index: Overall Quick:

	Position	Code	Observation	Video (sec)	Grade
203-0	060				
$\overline{}$	0.	AMH	Manhole	10	NA
	0.	MWL	Water Level	21	NA
	\\\ <u>.</u> 0	DAZ(S01)	Deposits Attached Other	32	M 2
	10.6	CL	Crack Longitudinal	65	S 2
	10.6	IS	Infil Stain	76	NA
	32.6	TF	Tap Factory	132	NA
	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	TF	Tap Factory	170	NA
\	71.6	TF	Tap Factory	235	NA
	98.0	TF	Tap Factory	299	NA
_	130.0	TF	Tap Factory	375	NA
	146.9	TF	Tap Factory	422	NA
Ш.	//178.3	TF	Tap Factory	497	NA
	178.3	DAE	Deposits Attached Encrustation	509	M 2
	209.7	TFD	Tap Factory Defective	583	M 2
	251.6	AMH	Manhole	678	NA
ш.	251.6	DAZ(F01)	Deposits Attached Other	689	M 2
203					

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-203-060

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:


Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO




Code: DAZ

Description: **Deposits Attached Other**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 7 Clock To: 5 1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: **S01** Within 8" of Joint: YES Remarks: WANDER




Code: CL

Description: Crack Longitudinal

Distance (ft): 10.6
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 12

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:

Remarks:



Code: IS

Description: Infil Stain

Distance (ft): 10.6
Structural Grade: 0
O&M Grade: 7
Clock Start/From: 5
1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Description: Tap Factory

Distance (ft): 32.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 45.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory

Distance (ft): 71.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**


Description: Tap Factory

Distance (ft): 98.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory


Distance (ft): 130.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 146.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 12

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory

Distance (ft): 178.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 178.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 3
Clock To: 7
1st Value:
2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO Remarks: TAP



Description: Tap Factory Defective

Distance (ft): 209.7
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: UNKNOWN DEPOSITS BLOCKING

TAP



Code: AMH
Description: Manhole

Distance (ft): 251.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-203-065



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 251.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks: WANDER