

Profile/Ph	oto Observatior	n Report			RedZon
Date: Pipe Length (ft P.O.#: Customer:	03/22/2018 :): 318.8	Weather: Owner: Surveyor: Clean Date:	NA Selasie Honu 01/01/1900	Coding: Pre Clean: PSR: Shape:	PACP 6.0 No Pre-Cleaning P-208-003-004 C
Street:	OFF MINNESOTA S	ST	Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Light Highway		Tape/Media #:		
Purpose:	Routine Assessme	ent	Dia/Height:	8"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:	F_S_P_C at 0 ft bu	ild up on the pipe			
Location Detai	ls:		Direction of Survey:	Downstream	
US MH:	M-208-004	DS MH: N	1-208-003	Total Length Surveyed (ft)	: 2.1
0&M Index:	3.00	O&M Quick:	4121	O&M Rating:	6.00
Structural Index:	0.00	Structural Quic	k: 0000	Structural Rating:	0.00
Overall Index:	3.00	Overall Quick:	4121	Overall Rating:	6.00





Code: Description:	DAE Deposits Attached Encrustation
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	4
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	30.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: IW Description: Infil Weeper

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-208-004




Code:	MWL
Description:	Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	

Code:	
Description:	

MSA	
Abando	ned Survey



Distance (ft):	2.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	camera stopped