## **Profile/Photo Observation Report**



Date: 03/23/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 204.1 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: Surveyor: Jen Costello PSR: P-208-006-007

P.O.#: Surveyor: Jen Costello PSR: P-208-006-007

Customer: Clean Date: 01/01/1900 Shape: C

Street: ALLEY BETWEEN MINNESOTA ST & V Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 8"
Use: Sanitary Material: VCP

Drain Area: **NA** Lining:

Category: NA

Comment: P\_C at 19 ft CU .Flow direction wrong

Location Details: Direction of Survey: Upstream

US MH: M-208-007 DS MH: M-208-006 Total Length Surveyed (ft): 20.7

4.00 4.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 4.00 4.00 Overall Quick: Overall Rating: Overall Index:

Р	osition	Code	Observation	Video (sec)	Grade
A(208 <del>)</del> 006					
0.		AMH	Manhole	10	NA
0. //	)	MWL	Water Level	21	NA
\_0.	)	MCU	Camera Underwater	32	M 4
20	0.7	MSA	Abandoned Survey	85	NA

Code:

Description:



Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-208-006

AMH

Manhole



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 100.000

Continuous Index:

Within 8" of Joint:

Remarks:

100.000

NO

Code: MCU
Description: Camera Underwater



Distance (ft): .0

Structural Grade: **0**O&M Grade: **4** 

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 20.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO Remarks: NCU