
Profile/Ph	oto Observatior	n Report				RedZor
Date:	03/20/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft	:): <b>207.0</b>	Owner:	NA		Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	John Kugl	maier	PSR:	P-108-054-021
Customer:		Clean Date:	: 01/01/19	00	Shape:	С
Street:	W 61ST AVE & S L	ST AVE & S LIVERPOOL RD		Flow Control:		
City:	Hobart, IN		Year Renev	ved:		
Location:	Light Highway		Tape/Medi	a #:		
Purpose:	Routine Assessme	nt	Dia/Height:	:	10"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:	P_C at 53 ft nothir	ng visible .Flow d	lirection wron	g		
Location Detai	ls:		Direction o	f Survey:	Upstream	
US MH:	M-208-021	DS MH:	M-108-054	-	Fotal Length Surveyed (ft)	: <b>54.4</b>
D&M Index:	0.00	O&M Quick:	:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Q	uick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quic	:k:	0000	Overall Rating:	0.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-108-054



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	39.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:MSADescription:Abandoned Survey

Distance (ft): 54.4 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: NO Unknown Remarks:

Thursday, November 16, 2023