
Profile/Ph	oto Observation	Report				RedZon
Date:	03/22/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft): 149.5	Owner:	NA		Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	Selasie Ho	nu	PSR:	P-208-026-025
Customer:		Clean Date	: 01/01/190	00	Shape:	С
Street:	OFF MINNESOTA S	т	Flow Contro	ol:	Not Controlled	
City:	Hobart, IN		Year Renew	ed:		
Location:	Light Highway		Tape/Media	ı #:		
Purpose:	Routine Assessme	nt	Dia/Height:		8"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:	Flow direction wro	ong				
Location Detai	ls:		Direction of	Survey:	Downstream	
US MH:	M-208-025	DS MH:	M-208-026	Т	otal Length Surveyed (ft)	: 158.4
0&M Index:	1.00	O&M Quick	:	1200	O&M Rating:	2.00
Structural Index	0.00	Structural C	Quick:	0000	Structural Rating:	0.00
Overall Index:	1.00	Overall Qui	ck:	1200	Overall Rating:	2.00






Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-208-025



Code: MWL Description: Water Level

.0
0
0
5.000
NO



Code: Description:	RFJ Roots Fine Joint
Distance (ft):	12.0
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	12
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	RFJ
Description:	Roots Fine Joint

Distance (ft):	52.0
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	11
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	158.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-208-026