

Profile/Ph	oto Observation	n Report				RedZone
Date:	03/22/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft	): <b>138.8</b>	Owner:	NA		Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	Selasie Ho	onu	PSR:	P-208-027-026
Customer:		Clean Date	: <b>01/01/19</b>	00	Shape:	С
Street:	OFF MINNESOTA S	ST	Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renew	ved:		
Location:	Light Highway		Tape/Medi	a #:		
Purpose:	Routine Assessme	nt	Dia/Height:		8"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:	Flow direction wro	ong				
Location Detai	ls:		Direction o	f Survey:	Upstream	
US MH:	M-208-026	DS MH:	M-208-027	Тс	otal Length Surveyed (ft)	: <b>130.6</b>
0&M Index:	0.00	O&M Quick	:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural C	uick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quid	ck:	0000	Overall Rating:	0.00





Code:	АМН
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-208-027



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TFC Tap Factory Capped
Distance (ft):	77.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:AMHDescription:Manhole

Distance (ft):	130.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-208-026