

Profile/Pho	to Observation I	Report				RedZone R 0 B 0 T I C S
Date:	03/22/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft):	394.8	Owner:	NA		Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	Selasie H	onu	PSR:	P-209-029-031
Customer:		Clean Date:	01/01/19	00	Shape:	С
Street:	W 61ST AVE & COLO	RADO ST	Flow Contr	ol:	Not Controlled	
City:	Hobart, IN		Year Renev	ved:		
Location:	Light Highway		Tape/Medi	a #:		
Purpose:	Routine Assessment		Dia/Height	:	10"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:	P_C at 93 ft nothing visible . Flow direction wrong					
Location Details:			Direction o	f Survey:	Upstream	
US MH: N	1-208-031	DS MH:	M-209-029		Total Length Surveyed (ft):	94.8
0&M Index:	0.00	O&M Quick:		0000	O&M Rating:	0.00
tructural Index:	0.00	Structural Q	uick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quic	k:	0000	Overall Rating:	0.00


D

177





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-209-029




Code: Description:

Water Level

MWL

Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:	5.000	
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:		



Code:	MSA
Description:	Aban

Abandoned Survey

Distance (ft):	94.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	camera stopped