


## Profile/Photo Observation Report



|                   |                   |             |                       |            |                        |
|-------------------|-------------------|-------------|-----------------------|------------|------------------------|
| Date:             | <b>03/20/2018</b> | Weather:    |                       | Coding:    | <b>PACP 6.0</b>        |
| Pipe Length (ft): | <b>307.9</b>      | Owner:      | <b>NA</b>             | Pre Clean: | <b>No Pre-Cleaning</b> |
| P.O.#:            |                   | Surveyor:   | <b>John Kuglmaier</b> | PSR:       | <b>P-209-005-006</b>   |
| Customer:         |                   | Clean Date: | <b>01/01/1900</b>     | Shape:     | <b>C</b>               |


|                   |  |                             |                       |
|-------------------|--|-----------------------------|-----------------------|
| Street:           | <b>E 62ND PL</b>   | Flow Control:               | <b>Not Controlled</b> |
| City:             | <b>Hobart, IN</b>  | Year Renewed:               |                       |
| Location:         | <b>Light Highway</b>   | Tape/Media #:               |                       |
| Purpose:          | <b>Routine Assessment</b>                                      | Dia/Height:                 | <b>10"</b>            |
| Use:              | <b>Sanitary</b>  | Material:                   | <b>VCP</b>            |
| Drain Area:       | <b>NA</b>  | Lining:                     |                       |
| Category:         | <b>NA</b>  |                             |                       |
| Comment:          | <b>F_S_R_M at 1 ft sludge and debris. Flow direction wrong</b> |                             |                       |
| Location Details: |  | Direction of Survey:        | <b>Upstream</b>       |
| US MH:            | <b>M-209-006</b>   | DS MH:                      | <b>M-209-005</b>      |
|                   |  | Total Length Surveyed (ft): | <b>3.0</b>            |

|                   |             |                   |             |                    |             |
|-------------------|-------------|-------------------|-------------|--------------------|-------------|
| O&M Index:        | <b>0.00</b> | O&M Quick:        | <b>0000</b> | O&M Rating:        | <b>0.00</b> |
| Structural Index: | <b>0.00</b> | Structural Quick: | <b>0000</b> | Structural Rating: | <b>0.00</b> |
| Overall Index:    | <b>0.00</b> | Overall Quick:    | <b>0000</b> | Overall Rating:    | <b>0.00</b> |

|  | Position | Code | Observation      | Video (sec) | Grade |
|--|----------|------|------------------|-------------|-------|
|  |          |      |                  |             |       |
|  | .0       | AMH  | Manhole          | 11          | NA    |
|  | .0       | MWL  | Water Level      | 22          | NA    |
|  | 3.0      | MSA  | Abandoned Survey | 39          | NA    |

Code: AMH

Description: Manhole



Distance (ft): .0

Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:

1st Value:

2nd Value:

Value Percent:


Continuous Index:

Within 8" of Joint: NO

Remarks: M-209-005

---


|              |                    |
|--------------|--------------------|
| Code:        | <b>MWL</b>         |
| Description: | <b>Water Level</b> |



|                     |               |
|---------------------|---------------|
| Distance (ft):      | <b>.0</b>     |
| Structural Grade:   | <b>0</b>      |
| O&M Grade:          | <b>0</b>      |
| Clock Start/From:   |               |
| Clock To:           |               |
| 1st Value:          |               |
| 2nd Value:          |               |
| Value Percent:      | <b>35.000</b> |
| Continuous Index:   |               |
| Within 8" of Joint: | <b>NO</b>     |
| Remarks:            |               |

---

|              |                         |
|--------------|-------------------------|
| Code:        | <b>MSA</b>              |
| Description: | <b>Abandoned Survey</b> |



|                     |                |
|---------------------|----------------|
| Distance (ft):      | <b>3.0</b>     |
| Structural Grade:   | <b>0</b>       |
| O&M Grade:          | <b>0</b>       |
| Clock Start/From:   |                |
| Clock To:           |                |
| 1st Value:          |                |
| 2nd Value:          |                |
| Value Percent:      |                |
| Continuous Index:   |                |
| Within 8" of Joint: | <b>NO</b>      |
| Remarks:            | <b>Unknown</b> |