## **Profile/Photo Observation Report**



Date: 03/22/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 347.0 Owner: NA Pre Clean: No Pre-Cleaning
P.O.#: Surveyor: Selasie Honu PSR: P-209-028-029

Customer: Clean Date: 01/01/1900 Shape: C

Street: COLORADO ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 10"
Use: Sanitary Material: PVC

Drain Area: NA Lining:

Category: NA

Comment: P\_C at 243 ft nothing visible .Flow direction

Location Details: Direction of Survey: **Downstream** 

US MH: M-209-029 DS MH: M-209-028 Total Length Surveyed (ft): 244.4

0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:

	Code	Observation	Video (sec)	Grade
09-029				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
25.3	TF	Tap Factory	84	NA
48.1	MWL	Water Level	141	NA
244.4	MSA	Abandoned Survey	545	NA

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-209-029		

 $\mathsf{AMH}$ 



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 30.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO

Code: TF Description: **Tap Factory** 

Distance (ft): 25.3 Structural Grade: 0

O&M Grade: 0 Clock Start/From: 2


Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:





Code: MWL

Description: Water Level

Distance (ft): 48.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 244.4
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: camera stopped