Profile/Photo Observation Report




| Profile/Photo Observation Report | | | | | | | | |
|---|--|--|-----------------------------|--------|---|---|--|--|
| Date: Pipe Length (ft) P.O.#: Customer: | 04/07/2018): 13-1 City of Hobart | Weather: Owner: Surveyor: Clean Date: | City of Hoba M. Pielacha | rt | Coding: Pre Clean: PSR: Shape: | PACP 6.0 No Pre-Cleaning M-303-001-M-304-003 C | | |
| Street: | Old Ridge Road | | Flow Control: | | Not Controlled | | | |
| City: | Hobart, IN | | Year Renewed | : | | | | |
| Location: | Light Highway | | Tape/Media# | : | DEP 13 | | | |
| Purpose: | Routine Assessment | | Dia/Height: | | 18" | | | |
| Use: | Sanitary | | Material: | | VCP | | | |
| Drain Area: | | | Lining: | | | | | |
| Category: | NA | | | | | | | |
| Comment: | | | | | | | | |
| Location Detail | s: | | Direction of Su | ırvey: | Downstream | | | |
| US MH: | M-303-001 | DS MH: | M-304-003 | ٦ | Total Length Surveyed (ft): | 356.1 | | |
| D&M Index: | 2.13 | O&M Quick: | 4 | 131 | O&M Rating: | 49.00 | | |
| Structural Index: | 2.00 | — Structural Qui | ck: 2 | 100 | Structural Rating: | 2.00 | | |
| Overall Index: | 2.13 | — Overall Quick: | 4 | 131 | Overall Rating: | 51.00 | | |

| | Position | Code | Observation | Video (sec) | Grade |
|-----------|----------|----------|--------------------------------|-------------|-------|
| 303- | 001 | | | | |
| \bigvee | 0. // | AMH | Manhole | 0 | NA |
| ш | 0. | MWL | Water Level | 14 | NA |
| ш | 125.6 | DAE | Deposits Attached Encrustation | 265 | M 2 |
| ш | 181.4 | IR | Infil Runner | 349 | M 4 |
| ш | 191.6 | DAE | Deposits Attached Encrustation | 371 | M 2 |
| ш | 201.4 | DAE | Deposits Attached Encrustation | 392 | M 2 |
| ш | 206.5 | DAE | Deposits Attached Encrustation | 408 | M 2 |
| Ш. | 221.6 | DAE(S01) | Deposits Attached Encrustation | 438 | M 2 |
| | 258.1 | ТВА | Tap Break-in Active | 488 | NA |
| ш | 258.1 | DAE(F01) | Deposits Attached Encrustation | 503 | M 2 |
| ш | 259.2 | CL | Crack Longitudinal | 511 | S 2 |
| ш | 268.9 | TFC | Tap Factory Capped | 534 | NA |
| | 285.6 | DAE(S02) | Deposits Attached Encrustation | 574 | M 2 |
| | 335.7 | ID | Infil Dripper | 642 | M 3 |
| | 335.7 | DAE(F02) | Deposits Attached Encrustation | 655 | M 2 |
| ш | 356.1 | AMH | Manhole | 692 | NA |
| Ш | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |



M(304)003

| Code: Description: | AMH Manhole |
|-----------------------|----------------|
| Distance (ft): | .0 |
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Continuous Index: | |
| Within 8" of Joint: | NO |
| Remarks: | M-303-001 |
| | |



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

10.000



Code: DAE

Description: **Deposits Attached Encrustation**

Distance (ft): 125.6 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 7 Clock To: 11 1st Value:

2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: IR

Description: **Infil Runner**

Distance (ft): 181.4 Structural Grade: 0 O&M Grade: 4 Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAE

Description: **Deposits Attached Encrustation**

Distance (ft): 191.6 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 1 5 Clock To: 1st Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

2nd Value:

YES



Code: DAE

Description: **Deposits Attached Encrustation**

Distance (ft): 201.4 Structural Grade: 0 2 O&M Grade: Clock Start/From: 7 Clock To: 11

1st Value: 2nd Value:

5.000 Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAE

Description: **Deposits Attached Encrustation**

Distance (ft): 206.5 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 7 Clock To: 11 1st Value:

2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 221.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: YES

Remarks:



Code: TBA

Description: Tap Break-in Active

Distance (ft): 258.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:


1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:

Friday, October 1, 2021 6



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 258.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks:



Code: CL

Description: Crack Longitudinal

Distance (ft): 259.2
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:

Friday, October 1, 2021 7



Code: TFC

Description: **Tap Factory Capped**

Distance (ft): 268.9 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 2

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: DAE

Description: **Deposits Attached Encrustation**

5.000

Distance (ft): 285.6 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 7 5 Clock To: 1st Value:

2nd Value: Value Percent:

Continuous Index: **S02** Within 8" of Joint: YES

Remarks:



Code: ID

Description: **Infil Dripper**

Distance (ft): 335.7 Structural Grade: 0 3 O&M Grade: Clock Start/From: 11

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAE

Description: **Deposits Attached Encrustation**

Distance (ft): 335.7 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 7 5 Clock To: 1st Value:

5.000 Value Percent: Continuous Index: F02 Within 8" of Joint: NO

Remarks:

2nd Value:



Code: AMH
Description: Manhole

Distance (ft): 356.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-304-003