
Profile/Ph	oto Observation	Report			RedZone
Date:	09/29/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft	): <b>18.4</b>	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Selasie Honu	PSR:	P-303-010-009
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	39th. Ave.		Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Light Highway		Tape/Media #:		
Purpose:	Routine Assessment	t	Dia/Height:	12"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Detail	s:		Direction of Surve	ey: Downstream	
US MH:	M-303-010	DS MH:	M-303-009	Total Length Surveyed (ft):	9.7
O&M Index:	3.00	O&M Quick:	3100	O&M Rating:	3.00
Structural Index:	4.00	 Structural Qu	ick: 4100	Structural Rating:	4.00
Overall Index:	3.50	Overall Quick	4131	Overall Rating:	7.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-303-010



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 5.000 Continuous Index: Within 8" of Joint: NO Remarks:



Code:	MWLS
Description:	Water Level Sag


Distance (ft):	.0
Structural Grade:	4
O&M Grade:	3
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	60.000
Continuous Index:	S01
Within 8" of Joint:	NO
Remarks:	



Code:MWLSDescription:Water Level Sag

Distance (ft):	6.3
Structural Grade:	4
O&M Grade:	3
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	60.000
Continuous Index:	F01
Within 8" of Joint:	NO
Remarks:	

Code: Description: MSA Abandoned Survey



Value Percent: Continuous Index: Within 8" of Joint: NO Remarks: camera stopped

9.7

0

0

