## **Profile/Photo Observation Report**



Date: 03/28/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 313.9 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: Surveyor: Selasie Honu P-303-023-022

Customer: Clean Date: 01/01/1900 Shape: C

Street: KENWOOD ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-303-022 DS MH: M-303-023 Total Length Surveyed (ft): 29.8

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2100 2.00 Overall Rating: Overall Index: Overall Quick:

Position	Code	Observation	Video (sec)	Grade
303-023				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
29.8	MSA	Abandoned Survey	92	NA
29.8	DSZ	Deposits Settled Other	103	M 2

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:  O&M Grade:  Clock Start/From:	0
Clock To:  1st Value:	
2nd Value: Value Percent:	
Continuous Index: Within 8" of Joint: Remarks:	NO M-303-023

**AMH** 



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:


Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO



Code: MSA

Description: **Abandoned Survey** 


Distance (ft): 29.8 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks: camera stopped

NO



Code: **DSZ** 

Description: Deposits Settled Other

Distance (ft): 29.8
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 5

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks: mixed material