## **Profile/Photo Observation Report**



Date: 03/28/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 313.9 Owner: NA Pre Clean: **Not Known** P.O.#: P-303-023-022 Surveyor: PSR: Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: KENWOOD ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: **NA** Lining:

Category: NA

Comment:


Location Details: Direction of Survey: Downstream

US MH: M-303-022 DS MH: M-303-023 Total Length Surveyed (ft): 16.5

3.50 7.00 O&M Index: O&M Quick: O&M Rating: 2.00 2100 2.00 Structural Quick: Structural Rating: Structural Index: 9.00 3.00 Overall Index: Overall Quick: Overall Rating:


	Code	Observation	Video (sec)	Grade
303-022				
0.	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
12.7	MWLS	Water Level Sag	58	S 2
15.1	MCU	Camera Underwater	74	M 4
16.5	MSA	Abandoned Survey	89	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-303-022

 $\mathsf{AMH}$ 



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO



Code: **MWLS** 

Description: **Water Level Sag** 

Distance (ft): 12.7 Structural Grade: 2 O&M Grade: 3 Clock Start/From:


Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MCU

Description: Camera Underwater

Distance (ft): 15.1
Structural Grade: 0
O&M Grade: 4

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: Within 8" of Joint:

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 16.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: camera stopped