## **Profile/Photo Observation Report**



Date: 09/25/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 315.8 Owner: NA Pre Clean: **Not Known** P.O.#: **Justin Gonzales** PSR: Surveyor: P-303-029-028

Customer: Clean Date: 01/01/1900 Shape: C

Street: KENWOOD ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Downstream** 

US MH: M-303-028 DS MH: M-303-029 Total Length Surveyed (ft): 265.0

2.33 21.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.33 21.00 Overall Quick: Overall Rating: Overall Index:

Position	Code	Observation	Video (sec)	Grade
303-028				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
59.0	RMJ	Roots Medium Joint	150	M 3
/59.0	DAE	Deposits Attached Encrustation	162	M 2
64.8	TF	Tap Factory	184	NA
112.7	TF	Tap Factory	292	NA
/130.1	TFD	Tap Factory Defective	339	M 2
156.1	RFJ	Roots Fine Joint	403	M 1
156.1	IS	Infil Stain	414	NA
171.4	RMJ	Roots Medium Joint	457	M 3
176.9	TFI	Tap Factory Intruding	479	M 2
199.5	TF	Tap Factory	537	NA
246.6	TFD	Tap Factory Defective	643	M 2
263.1	RMB	Roots Medium Barrel	688	M 4
263.3	TFD	Tap Factory Defective	701	M 2
265.0	MSA	Abandoned Survey	716	NA

Code:

Description:



(6)	_		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-303-028		

AMH

Manhole



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: RMJ

Description: **Roots Medium Joint** 

Distance (ft): 59.0 Structural Grade: 0 O&M Grade: 3 Clock Start/From: 7 Clock To: 12 1st Value:

2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 59.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 1
Clock To: 5
1st Value:

2nd Value:


Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: TF

Description: Tap Factory

Distance (ft): 64.8
Structural Grade: 0

O&M Grade: 0


Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 112.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value:

4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TFD** 

Description: Tap Factory Defective

Distance (ft): 130.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 10


Clock To:

2nd Value:

1st Value: **4.000** 

Value Percent: Continuous Index: Within 8" of Joint:

Remarks: ROOTS COMING FROM TAP



Code: RFJ

Description: Roots Fine Joint


Distance (ft): 156.1
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 7
Clock To: 12

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: IS

Description: Infil Stain

Distance (ft): 156.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 8
Clock To: 12
1st Value:
2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 171.4
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 7
Clock To: 5
1st Value:

2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: TFI

Description: Tap Factory Intruding

Distance (ft): 176.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2

Clock To:

 1st Value:
 4.000

 2nd Value:
 1.000

Value Percent: Continuous Index: Within 8" of Joint:

Remarks: ROOTS SURROUNDING OUTSIDE OF

**TAP** 



Code: **TF** 

Description: Tap Factory

Distance (ft): 199.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:


1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Description: Tap Factory Defective




Distance (ft): 246.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: RM INSIDE OF TAP



Code: RMB

Description: Roots Medium Barrel

Distance (ft): 263.1
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 7
Clock To: 11

1st Value: 2nd Value:


Value Percent: 30.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TFD** 

Description: Tap Factory Defective


Distance (ft): 263.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: RM COMING FROM TAP



Code: MSA

Description: Abandoned Survey

Distance (ft): 265.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks: CANNOT PASS RMB