Profile/Ph	oto Observation	Report			RedZone
Date:	09/26/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft): 416.1	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Selasie Honu	PSR:	P-303-038-039
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	ROCHE ST		Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Light Highway		Tape/Media #:		
Purpose:	Routine Assessmen	nt	Dia/Height:	10"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Detail	s:		Direction of Surve	y: Upstream	
US MH:	M-303-039	DS MH:	M-303-038	Total Length Surveyed (ft)	: 196.5
0&M Index:	2.50	O&M Quick:	4111	O&M Rating:	5.00
tructural Index:	2.00	Structural Qui	ck: 2100	Structural Rating:	2.00
Overall Index:	2.33	Overall Quick:	4121	Overall Rating:	7.00

	Position	Code	Observation	Video (sec)	Grade
M-303-038					
\leq	.0	AMH	Manhole	10	NA
— — (\ <u>.</u> 0	MWL	Water Level	21	NA
	12.8	IS	Infil Stain	58	NA
	18.2	DAE	Deposits Attached Encrustation	80	M 4
	18.2	FC	Fracture Circumferential	91	S 2
	33.1	TF	Tap Factory	132	NA
	40.1	RFJ	Roots Fine Joint	157	M 1
	65.5	IS	Infil Stain	219	NA
	95.8	TF	Tap Factory	291	NA
5	142.7	TF	Tap Factory	396	NA
/ Lect	185.9	TF	Tap Factory	494	NA
	196.5	MSA	Abandoned Survey	527	NA
Camera Direction	39				



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-303-038



Code: MWL Description: Water Level

.0
0
0
5.000
NO



Code: Description:	IS Infil Stain
Distance (ft):	12.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code:DAEDescription:Deposits Attached Encrustation

Distance (ft):	18.2
Structural Grade:	0
O&M Grade:	4
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	30.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	

.

Code:	FC
Description:	Fracture Circumferential
Distance (ft):	18.2
Structural Grade:	2
O&M Grade:	0
Clock Start/From:	8
Clock To:	4

electro car q i ronni	0	
Clock To:	4	
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	YES	
Remarks:		




Code:	TF
Description:	Tap Factory

Distance (ft):	33.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	RFJ
Description:	Roots Fine Joint
Distance (ft):	40.1
Structural Grade:	0
O&M Grade	1

40.1
0
1
8
4
YES




Code:	IS
Description:	Infil Stain

Distance (ft):	65.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code: Description:	TF Tap Factory
Distance (ft):	95.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:TFDescription:Tap Factory


Distance (ft):	142.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	



Code:	TF
Description:	Tap Factory
Distance (ft):	185.9
Structural Grade:	0
	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



MSA Abandoned Survey



Distance (ft):	196.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	camera stoppped

Thursday, November 16, 2023