Profile/Photo Observation Report




Profile/Photo Observation Report							
Date: Pipe Length (ft) P.O.#:	YES502259	Weather: Owner: Surveyor:	City of Hobart S. Bucklin	Coding: Pre Clean: PSR:	PACP 7.0 Heavy Cleaning P-303-047-LS004		
Customer:	City of Hobart	Clean Date:	10/25/2024	Shape:	С		
Street:	West 37th Avenu	West 37th Avenue		Not Controlled	I		
City:	Hobart, IN		Year Renewed:				
Location:	Easement/Right	of Way	Tape/Media #:				
Purpose:	Sewer System Ev	aluation Survey (SS	Dia/Height:	12"			
Use:	Sanitary Sewage	Pipe	Material:	VCP			
Drain Area:			Lining:	None			
Category:	NA						
Comment:							
Location Detail	s:		Direction of Survey	: Downstream			
US MH:	M-303-047	DS MH:	LS004	Total Length Surveyed (ft): 59.8		
O&M Index:	2.25	O&M Quick:	4122	O&M Rating:	9.00		
Structural Index:	3.00	Structural Qui	ick: 4121	Structural Rating:	6.00		
Overall Index:	2.50	Overall Quick:	4222	Overall Rating:	15.00		

Friday, March 21, 2025

	Position	Code	Observation	Video (sec)	Grade
303-0	047				
$\overline{}$	0. //	AMH	Manhole	0	NA
ш	0.	MWL	Miscellaneous Water Level	76	NA
ш	38.4	LD	Line Down	213	M 2
ш	51.4	MWLS(S01)	Miscellaneous Water Level Sag	265	S 2
ш	54.5	RFJ	Roots Fine Joint	331	M 1
ш	54.5	DAE	Deposits Attached Encrustation	340	M 2
ш	54.5	В	Broken	380	S 4
ш	55.4	RMB	Roots Medium Barrel	405	M 4
ш	57.2	MWLS(F01)	Miscellaneous Water Level Sag	447	S 2
ш	59.8	AWW	Access Point Wet Well	583	NA
ш					
ш					



Code:	AMH
Description:	Manhole
Distance (ft):	.0
Structural Grade	: 0
O&M Grade:	0
Clock Start/From	:
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index	x:
Within 8" of Join	t: NO
Remarks:	M-303-047



Code: MWL

Description: Miscellaneous Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5

Continuous Index:

Within 8" of Joint: N

Remarks:

5.000

NO

1/28/25 38.41 ft

Code: LD

Description: Line Down

Distance (ft): 38.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MWLS

Description: Miscellaneous Water Level Sag

Distance (ft): 51.4
Structural Grade: 2

O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: S01
Within 8" of Joint: NO

Remarks:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 54.5
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 7
Clock To: 5
1st Value:
2nd Value:
Value Percent:

Within 8" of Joint: YES

Remarks:

Continuous Index:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 54.5
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 1

Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: B
Description: Broken

·

Distance (ft): 54.5
Structural Grade: 4


O&M Grade: 0
Clock Start/From: 7
Clock To: 5

1st Value:
2nd Value:
Value Percent:

Continuous Index: Within 8" of Joint:

/ithin 8" of Joint: YES

Remarks:



Code: **RMB**

Description: **Roots Medium Barrel**

Distance (ft): 55.4 Structural Grade: 0 O&M Grade: 4 Clock Start/From: 7 Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **MWLS**

Description: **Miscellaneous Water Level Sag**

57.2 Distance (ft): Structural Grade: 2 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000 Continuous Index: F01 Within 8" of Joint: NO

Remarks:

6 Friday, March 21, 2025



Code: AWW

Description: Access Point Wet Well

Distance (ft): 59.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: LS004