


Profile/Ph	oto Observatior	n Report				RedZone
Date:	09/29/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft)): 227.7	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Justin G	onzales	PSR:	P-303-059-063
Customer:		Clean Date	e: 01/01/1	900	Shape:	C
Street:	W HANSEN BLVD	& S HANSEN BL	VD Flow Cont	rol:	Not Controlled	
City:	Hobart, IN		Year Rene	wed:		
Location:	Light Highway		Tape/Med	lia #:		
Purpose:	Routine Assessme	nt	Dia/Heigh	t:	10"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detail	S:		Direction	of Survey:	Downstream	
US MH:	M-303-063	DS MH:	M-303-059	Т	otal Length Surveyed (ft)	: 223.3
0&M Index:	0.00	O&M Quic	k:	0000	O&M Rating:	0.00
tructural Index:	0.00	Structural (Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Qu	ick:	0000	Overall Rating:	0.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-303-063



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	15.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	49.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	TF
Description:	Tap Factory

Distance (ft):	75.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	

Code: Description:	MGO General Observation
Distance (ft):	77.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	LIGHT FOG/STEAM



Code: AMH Description: Manhole

Distance (ft):	223.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-303-059