
Profile/Ph	oto Observatio	n Report			RedZone
Date:	04/05/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft): 403.0	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	PSR:	P-303-070-069
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	RIDGELAWN DR 8	& W 39TH AVE	Flow Control:	Not Controll	ed
City:	Hobart, IN		Year Renewed:		
Location:	Other		Tape/Media #:		
Purpose:	Not Known		Dia/Height:	12"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Detail	ls:		Direction of Su	rvey: Upstream	
US MH:	M-303-069	DS MH:	M-303-070	Total Length Surveyed (ft): 251.6
0&M Index:	0.00	O&M Quick:	00	00 O&M Rating:	0.00
Structural Index:	0.00	Structural Q	uick: OC	00 Structural Ratin	g: 0.00
Overall Index:	0.00	Overall Quic	k: 00	00 Overall Rating:	0.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-303-070



Code: MWL Description: Water Level

.0
0
0
5.000
NO



Code: Description:	MWL Water Level
Distance (ft):	79.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	20.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:MWLDescription:Water Level

Distance (ft):	90.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	
Description:	

MSA Abandoned Survey

Distance (ft):	251.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	DSF