Profile/Photo Observation Report



Profile/Photo Observation Report							
Date: Pipe Length (f P.O.#: Customer:	04/07/2018 it): 14-2 City of Hobart	Weather: Owner: Surveyor: Clean Date	City of Ho M. Pielac		Pre Clean: PSR:	PACP 6.0 No Pre-Cleaning M-304-003-M-304-002 C	
Street: City:	Old Ridge Road Hobart, IN		Flow Contr Year Renev	-	Not Controlled		
Location: Purpose:	Light Highway Reversal		Tape/Med Dia/Height		DEP 14 18"		
Use: Drain Area:	Sanitary		Material: Lining:		VCP		
Category: Comment:	NA						
Location Deta	ils:		Direction o	of Survey:	Upstream		
US MH:	M-304-003	DS MH:	M-304-002		Total Length Surveyed (ft):	37.6	
O&M Index:	0.00	O&M Quick	:	0000	O&M Rating:	0.00	
Structural Index	o.00	 Structural O	uick:	0000	Structural Rating:	0.00	
Overall Index:	0.00	Overall Quid	ck:	0000	Overall Rating:	0.00	

Friday, October 1, 2021

	Position	Code	Observation	Video (sec)	Grade
M(304)00)2				
	.0	AMH	Manhole	0	NA
	\.0	MWL	Water Level	14	NA
- 11	37.6	MSA	Abandoned Survey	79	NA
M-304-00	03				


Code:



Description: Manhole Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: NO Remarks: M-304-002

AMH

Friday, October 1, 2021 2



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Code:

15.000

Remarks:



MSA

Description: **Abandoned Survey**

Distance (ft): 37.6 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks: reverse complete

3 Friday, October 1, 2021