

# Profile/Photo Observation Report



|                   |                   |             |                        |            |                        |
|-------------------|-------------------|-------------|------------------------|------------|------------------------|
| Date:             | <b>04/19/2018</b> | Weather:    |                        | Coding:    | <b>PACP 6.0</b>        |
| Pipe Length (ft): | <b>290.4</b>      | Owner:      | <b>NA</b>              | Pre Clean: | <b>No Pre-Cleaning</b> |
| P.O.#:            |                   | Surveyor:   | <b>Justin Gonzales</b> | PSR:       | <b>P-305-001-031</b>   |
| Customer:         |                   | Clean Date: | <b>01/01/1900</b>      | Shape:     | <b>C</b>               |

|                   |                           |                             |                       |
|-------------------|---------------------------|-----------------------------|-----------------------|
| Street:           | <b>FOXCROFT STREET</b>    | Flow Control:               | <b>Not Controlled</b> |
| City:             | <b>Hobart, IN</b>         | Year Renewed:               |                       |
| Location:         | <b>Yard</b>               | Tape/Media #:               |                       |
| Purpose:          | <b>Routine Assessment</b> | Dia/Height:                 | <b>10"</b>            |
| Use:              | <b>Sanitary</b>           | Material:                   | <b>PVC</b>            |
| Drain Area:       | <b>NA</b>                 | Lining:                     | <b>Cured in Place</b> |
| Category:         | <b>NA</b>                 |                             |                       |
| Comment:          |                           |                             |                       |
| Location Details: |                           | Direction of Survey:        | <b>Downstream</b>     |
| US MH:            | <b>M-305-001</b>          | DS MH:                      | <b>M-405-031</b>      |
|                   |                           | Total Length Surveyed (ft): | <b>288.1</b>          |

|                   |             |                   |             |                    |               |
|-------------------|-------------|-------------------|-------------|--------------------|---------------|
| O&M Index:        | <b>2.29</b> | O&M Quick:        | <b>4A2J</b> | O&M Rating:        | <b>156.00</b> |
| Structural Index: | <b>0.00</b> | Structural Quick: | <b>0000</b> | Structural Rating: | <b>0.00</b>   |
| Overall Index:    | <b>2.29</b> | Overall Quick:    | <b>4A2J</b> | Overall Rating:    | <b>156.00</b> |

| Position         | Code     | Observation             | Video (sec) | Grade |
|------------------|----------|-------------------------|-------------|-------|
| <b>M-305-001</b> |          |                         |             |       |
| .0               | AMH      | Manhole                 | 10          | NA    |
| .0               | MWL      | Water Level             | 21          | NA    |
| .0               | DAZ(S01) | Deposits Attached Other | 32          | M 2   |
| 8.9              | MCU(S02) | Camera Underwater       | 61          | M 4   |
| 19.1             | MCU(F02) | Camera Underwater       | 93          | M 4   |
| 23.6             | MCU(S03) | Camera Underwater       | 114         | M 4   |
| 32.9             | MCU(F03) | Camera Underwater       | 144         | M 4   |
| 58.3             | IS       | Infil Stain             | 206         | NA    |
| 61.3             | MWL      | Water Level             | 224         | NA    |
| 80.3             | MCU(S04) | Camera Underwater       | 274         | M 4   |
| 88.5             | MCU(F04) | Camera Underwater       | 302         | M 4   |
| 118.0            | MCU(S05) | Camera Underwater       | 372         | M 4   |
| 122.1            | MCU(F05) | Camera Underwater       | 392         | M 4   |
| 134.6            | MWL      | Water Level             | 429         | NA    |
| 149.6            | MWL      | Water Level             | 470         | NA    |
| 194.8            | MCU(S06) | Camera Underwater       | 572         | M 4   |
| 201.8            | MCU(F06) | Camera Underwater       | 597         | M 4   |
| 231.1            | MWL      | Water Level             | 667         | NA    |
| 249.5            | TF       | Tap Factory             | 716         | NA    |
| 279.3            | MCU(S07) | Camera Underwater       | 787         | M 4   |
| 288.1            | MCU(F07) | Camera Underwater       | 816         | M 4   |
| 288.1            | DAZ(F01) | Deposits Attached Other | 828         | M 2   |
| 288.1            | AMH      | Manhole                 | 839         | NA    |
| <b>M-405-031</b> |          |                         |             |       |

Camera Direction  
↓



Code: **AMH**  
 Description: **Manhole**  
 Distance (ft): **.0**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **M-305-001**

---

Code: **MWL**  
Description: **Water Level**



Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **10.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:


---

Code: **DAZ**  
Description: **Deposits Attached Other**



Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **7**  
Clock To: **5**  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index: **S01**  
Within 8" of Joint: **YES**  
Remarks: **WANDER**

Code: **MCU**  
Description: **Camera Underwater**



Distance (ft): **8.9**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **S02**  
Within 8" of Joint: **NO**  
Remarks:


---

Code: **MCU**  
Description: **Camera Underwater**



Distance (ft): **19.1**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **F02**  
Within 8" of Joint: **NO**  
Remarks: **CAMERA EMERGED**

Code: **MCU**  
Description: **Camera Underwater**



Distance (ft): **23.6**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **S03**  
Within 8" of Joint: **NO**  
Remarks:

---

Code: **MCU**  
Description: **Camera Underwater**



Distance (ft): **32.9**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **F03**  
Within 8" of Joint: **NO**  
Remarks: **CAMERA EMERGED**

---

Code: **IS**  
Description: **Infil Stain**



Distance (ft): **58.3**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From: **12**  
Clock To: **5**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint:  
Remarks:

---


Code: **MWL**  
Description: **Water Level**



Distance (ft): **61.3**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **15.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:

---

Code: **MCU**  
Description: **Camera Underwater**




Distance (ft): **80.3**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **S04**  
Within 8" of Joint: **NO**  
Remarks:

---

Code: **MCU**  
Description: **Camera Underwater**



Distance (ft): **88.5**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **F04**  
Within 8" of Joint: **NO**  
Remarks: **CAMERA EMERGED**



Code: **MCU**  
Description: **Camera Underwater**

Distance (ft): **118.0**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **S05**  
Within 8" of Joint: **NO**  
Remarks:

---



Code: **MCU**  
Description: **Camera Underwater**

Distance (ft): **122.1**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **F05**  
Within 8" of Joint: **NO**  
Remarks:

---


Code: **MWL**  
Description: **Water Level**



Distance (ft): **134.6**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **20.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:

---


Code: **MWL**  
Description: **Water Level**



Distance (ft): **149.6**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **30.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:

---

Code: **MCU**  
Description: **Camera Underwater**




Distance (ft): **194.8**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **S06**  
Within 8" of Joint: **NO**  
Remarks:

---

Code: **MCU**  
Description: **Camera Underwater**




Distance (ft): **201.8**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **F06**  
Within 8" of Joint: **NO**  
Remarks: **WANDER**



Code: **MWL**  
Description: **Water Level**


Distance (ft): **231.1**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **50.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:



Code: **TF**  
Description: **Tap Factory**

Distance (ft): **249.5**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From: **11**  
Clock To:  
1st Value: **4.000**  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint:  
Remarks:

Code: **MCU**  
Description: **Camera Underwater**



Distance (ft): **279.3**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **S07**  
Within 8" of Joint: **NO**  
Remarks:

---


Code: **MCU**  
Description: **Camera Underwater**



Distance (ft): **288.1**  
Structural Grade: **0**  
O&M Grade: **4**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **F07**  
Within 8" of Joint: **NO**  
Remarks:

---

Code: **DAZ**  
Description: **Deposits Attached Other**



Distance (ft): **288.1**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **7**  
Clock To: **5**  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index: **F01**  
Within 8" of Joint: **YES**  
Remarks: **WANDER**

---

Code: **AMH**  
Description: **Manhole**



Distance (ft): **288.1**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks: **M-405-031**