Profile/Pho	oto Observation	Report			RedZone
Date: Pipe Length (ft)	04/18/2018 : 272.0	Weather: Owner:	NA	Coding: Pre Clean:	PACP 6.0 No Pre-Cleaning
P.O.#:		Surveyor:	Byrd Fitzgerald	PSR:	P-305-015-014
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	FOXCROFT STREET		Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Yard		Tape/Media #:		
Purpose:	Routine Assessment	:	Dia/Height:	10"	
Use:	Sanitary		Material:	XXX	
Drain Area:	NA		Lining:	Cured in Place	
Category:	NA				
Comment:					
Location Details	5:		Direction of Surve	ey: Downstream	
US MH:	M-305-015	DS MH:	M-305-014	Total Length Surveyed (ft):	274.8
0&M Index:	2.20	O&M Quick:	3124	O&M Rating:	11.00
tructural Index:	3.00		ck: 3100	Ŭ	3.00
Overall Index:	2.33	Overall Quick:	3224	Ŭ	14.00

	Position	Code	Observation	Video (sec)	Grade
M-305	5-015				
	.0	AMH	Manhole	10	NA
- 11	.0	MWL	Water Level	21	NA
- 11	35.8	DAGS(S01)	Deposits Attached Grease	104	M 2
- 11	46.8	DAGS(F01)	Deposits Attached Grease	138	M 2
	51.3	MWL	Water Level	158	NA
	51.6	TB	Tap Break-in	171	NA
- 11	55.1	LFAC	Lining Failure Abandoned Connection	190	NA
- 11	57.9	ТВ	Tap Break-in	208	NA
- 11	134.3	LFAC	Lining Failure Abandoned Connection	373	NA
5	/136.9	TBD	Tap Break-in Defective	391	M 3
ecti	// 150.2	ТВ	Tap Break-in	429	NA
Camera Direction	//195.7	ТВ	Tap Break-in	532	NA
nera	/ 195.7	DAGS	Deposits Attached Grease	543	M 2
La La	205.8	TBI	Tap Break-in Intruding	575	M 2
111	213.7	LFW	Lining Failure Wrinkled	602	S 3
111	218.4	LFAC	Lining Failure Abandoned Connection	623	NA
↓ III	220.5	LFAC	Lining Failure Abandoned Connection	639	NA
	_/// 274.8	AMH	Manhole	759	NA



AMH Manhole
.0
0
0
NO
M-305-015



Code: MWL Description: Water Level

.0
0
0
5.000
NO



Code:	DAGS
Description:	Deposits Attached Grease

Distance (ft):	35.8
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	S01
Within 8" of Joint:	NO
Remarks:	7 and 5 oclock



Code:DAGSDescription:Deposits Attached Grease

MWL

Water Level

Distance (ft):	46.8
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	F01
Within 8" of Joint:	NO
Remarks:	7 and 5 oclock



Distance (ft):	51.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	30.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	

Code:

Description:




Code:	ТВ
Description:	Tap Break-in

Distance (ft):	51.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description:	LFAC Lining Failure Abandoned Connection
Distance (ft):	55.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	тв
Description:	Tap Break-in

Distance (ft):	57.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description:	LFAC Lining Failure Abandoned Connection
Distance (ft):	134.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:TBDDescription:Tap Break-in Defective

Distance (ft):	136.9
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	3
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	partially blocked by debris



Code:	тв
Description:	Tap Break-in
Distance (ft):	150.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code:	ТВ
Description:	Tap Break-in

Distance (ft):	195.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	1
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	DAGS
Description:	Deposits Attached Grease
Distance (ft):	195.7

Distance (It).	133.7
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	2
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: TBI Description: Tap Break-in Intruding

Distance (ft): 205.8 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 10 Clock To: 1st Value: 4.000 2nd Value: 1.000 Value Percent: Continuous Index: Within 8" of Joint: Remarks:

	2. 1 . 18
	- Alter
	MATTER .
A.S.	and the second s

Code:	LFW
Description:	Lining Failure Wrinkled

Distance (ft):	213.7
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	2
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description: LFAC Lining Failure Abandoned Connection

218.
0
0
9
NO

8.4



Code: Description:	LFAC Lining Failure Abandoned Connection
Distance (ft):	220.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	274.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-305-014