Profile/Photo Observation Report



Date: **04/19/2018** Weather: Coding: **PACP 6.0**

Pipe Length (ft): 285.3 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: Surveyor: Byrd Fitzgerald PSR: P-305-025-024

Customer: Clean Date: 01/01/1900 Shape: C

Street: WOODLAND CT Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Yard Tape/Media #:

Purpose: Routine Assessment Dia/Height: 10"
Use: Sanitary Material: XXX

Drain Area: NA Lining: Cured in Place

Category: NA

Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-305-025 DS MH: M-305-024 Total Length Surveyed (ft): 264.9

4.00 212.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 4.00 212.00 Overall Quick: Overall Rating: Overall Index:

Po	sition	Code	Observation	Video (sec)	Grade
305-025					
0.		AMH	Manhole	10	NA
0.		MWL	Water Level	21	NA
0.//		MCU(S01)	Camera Underwater	32	M 4
\\ <u>16</u>	.2	MGO	General Observation	78	NA
\\26	.5	ТВ	Tap Break-in	110	NA
\\28	.1	TBA	Tap Break-in Active	125	NA
10	1.3	ТВ	Tap Break-in	283	NA
/10	5.5	ТВ	Tap Break-in	304	NA
// 18	0.7	ТВ	Tap Break-in	466	NA
/ _[19]	3.5	TBA	Tap Break-in Active	502	NA
25	4.4	ТВ	Tap Break-in	636	NA
26	4.9	AMH	Manhole	671	NA
26	4.9	MCU(F01)	Camera Underwater	683	M 4

Code:

Description:



·	
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-305-025

AMH

Manhole



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 100.000

Continuous Index:

Within 8" of Joint: NO Remarks: mcu



Code: MCU

Description: Camera Underwater


Distance (ft): .0
Structural Grade: 0
O&M Grade: 4
Clock Start/From:
Clock To:
1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

S01 NO



Code: MGO

Description: General Observation

Distance (ft): 16.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: rear camera/mcu



Code: TB


Description: Tap Break-in

Distance (ft): 26.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TBA

Description: Tap Break-in Active

Distance (ft): 28.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:


1st Value:

4.000

4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TB


Description: Tap Break-in

Distance (ft): 101.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TB

Description: Tap Break-in

4.000

Distance (ft): 105.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:


1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Code: TB

Description: Tap Break-in




Distance (ft): 180.7 Structural Grade: 0

O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TBA

Description: Tap Break-in Active


Distance (ft): 193.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TB

Description: Tap Break-in

Distance (ft): 254.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:



Code: AMH
Description: Manhole

Distance (ft): 264.9
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To: 1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-305-024



Code: MCU

Description: Camera Underwater

Distance (ft): 264.9
Structural Grade: 0
O&M Grade: 4

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: F01
Within 8" of Joint: NO