Profile/Photo Observation Report



Date: **04/17/2018** Weather: Coding: **PACP 6.0**

Pipe Length (ft): 304.5 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: Surveyor: Justin Gonzales PSR: P-305-037-029

Customer: Clean Date: 01/01/1900 Shape: C

Street: CRABAPPLE LN & WILDROSE DR Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Sidewalk Tape/Media #:

Purpose: Routine Assessment Dia/Height: 10"
Use: Sanitary Material: PVC

Drain Area: NA Lining: Cured in Place

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-305-029 DS MH: M-305-037 Total Length Surveyed (ft): 300.3

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

Position	Code	Observation	Video (sec)	Grade
305-037				
.0	AMH	Manhole	10	NA
0.0	MWL	Water Level	21	NA
117.6	MWL	Water Level	268	NA
135.2	MWL	Water Level	315	NA
146.4	MWL	Water Level	349	NA
157.2	IS	Infil Stain	382	NA
171.9	MWL	Water Level	423	NA
189.4	MWL	Water Level	469	NA
218.5	IS	Infil Stain	539	NA
265.0	MWL	Water Level	643	NA
297.9	MWL	Water Level	720	NA
300.3	AMH	Manhole	736	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-305-037

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

Description:

Distance (ft):

Water Level

117.6

NO

Code: MWL



Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 30.000

Continuous Index:

Within 8" of Joint: NO



Code: MWL

Description: Water Level

Distance (ft): 135.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MWL

Description: Water Level

Distance (ft): 146.4
Structural Grade: 0

O&M Grade: Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 40.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO

0



Code: IS

Description: Infil Stain

Distance (ft): 157.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:

Remarks:



Code: MWL

Description: Water Level

Distance (ft): 171.9
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO



Code: MWL

Description: Water Level

Distance (ft): 189.4
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 40.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: IS

Description: Infil Stain

Distance (ft): 218.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1
Clock To: 4

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: MWL

Description: Water Level

Distance (ft): 265.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MWL

Description: Water Level

Distance (ft): 297.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 30.000

Continuous Index:

Within 8" of Joint: NO



Code: AMH
Description: Manhole

Distance (ft): 300.3
Structural Grade: 0

O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks: M-305-029