## **Profile/Photo Observation Report**



Date: **04/18/2018** Weather: Coding: **PACP 6.0** 

Pipe Length (ft): 187.5 Owner: NA Pre Clean: No Pre-Cleaning
P.O.#: Surveyor: Byrd Fitzgerald PSR: P-305-031-030

Customer: Clean Date: 01/01/1900 Shape: C

Street: FOXCROFT STREET Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Yard Tape/Media #:

Purpose: Routine Assessment Dia/Height: 10"
Use: Sanitary Material: XXX

Drain Area: NA Lining: Cured in Place

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-305-031 DS MH: M-305-030 Total Length Surveyed (ft): 285.6

2.00 2200 4.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2200 4.00 Overall Rating: Overall Index: Overall Quick:

305-X	)30				
$\overline{}$	0. //	AMH	Manhole	10	NA
Щ	0.	MWL	Water Level	21	NA
Ш	18.6	ТВ	Tap Break-in	70	NA
ш	53.2	LFAC	Lining Failure Abandoned Connection	151	NA
	59.8	ТВ	Tap Break-in	176	NA
Ш	79.6	ТВ	Tap Break-in	227	NA
Ш	125.7	LFAC	Lining Failure Abandoned Connection	331	NA
ш	128.0	LFAC	Lining Failure Abandoned Connection	348	NA
ш	//140.1	ТВ	Tap Break-in	384	NA
ш.	// 140.1	DAZ	Deposits Attached Other	395	M 2
	145.7	ТВ	Tap Break-in	418	NA
Ш	203.4	LFAC	Lining Failure Abandoned Connection	545	NA
+	205.6	LFAC	Lining Failure Abandoned Connection	560	NA
ш	218.4	ТВ	Tap Break-in	597	NA
ш	220.5	ТВ	Tap Break-in	613	NA
Ш.	271.5	LFAC	Lining Failure Abandoned Connection	727	NA
Ш	274.0	LFAC	Lining Failure Abandoned Connection	743	NA
	282.4	DSZ	Deposits Settled Other	771	M 2
+	285.6	AMH	Manhole	789	NA

Code:



Manhole		
.0		
0		
0		
NO		
M-305-030		

**AMH** 



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO

Code: TB

Description: Tap Break-in



Distance (ft): 18.6 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 2

Clock To:

Remarks:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: LFAC

Description: Lining Failure Abandoned

Connection

Distance (ft): 53.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 9

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: TB

Description: Tap Break-in

Distance (ft): 59.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 11

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TB

Description: Tap Break-in

Distance (ft): 79.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: LFAC

Description: Lining Failure Abandoned

Connection

Distance (ft): 125.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **LFAC** 

Description: **Lining Failure Abandoned** 

Connection

Distance (ft): 128.0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 3

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



TB Code:

Description: Tap Break-in

Distance (ft): 140.1 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 1

Clock To:

4.000 1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 140.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2
Clock To: 5
1st Value:

2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: TB

Description: Tap Break-in

Distance (ft): 145.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: LFAC

Description: Lining Failure Abandoned

Connection

Distance (ft): 203.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: LFAC

Description: Lining Failure Abandoned

Connection

Distance (ft): 205.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: TB

Description: Tap Break-in

Distance (ft): 218.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Distance (ft): 220.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:





Code: LFAC

Description: Lining Failure Abandoned

Connection

Distance (ft): 271.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: LFAC

Description: Lining Failure Abandoned

NO

Connection

Distance (ft): 274.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint:



Code: DSZ

Description: Deposits Settled Other

Distance (ft): 282.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 6

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks: tissue/debris



Code: AMH
Description: Manhole

Distance (ft): 285.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-305-031