Profile/Pho	oto Observation	Report			RedZone
Date: Pipe Length (ft) P.O.#: Customer:	04/17/2018 : 298.9	Weather: Owner: Surveyor: Clean Date:	NA Justin Gonzales 01/01/1900	Pre Clean: PSR:	PACP 6.0 No Pre-Cleaning P-305-038-037 C
Street: City: Location:	FOXCROFT STREET Hobart, IN Sidewalk		Flow Control: Year Renewed: Tape/Media #:	Not Controlled	
Purpose: Use:	Routine Assessme Sanitary	nt	Dia/Height: Material:	10" PVC	
Drain Area: Category:	NA NA		Lining:	Cured in Place	
Comment: Location Details US MH:	M_T_P_C at 415 ft 5: M-305-038		Direction of Survey: /-305-037	Upstream Total Length Surveyed (ft):	415.4
0&M Index:	2.00	O&M Quick:	3121	O&M Rating:	6.00
tructural Index:	0.00	Structural Quic	:k: 0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quick:	3121	Overall Rating:	6.00

		Position	Code	Observation	Video (sec)	Grade
M(305-03	7				
Ň	\leq	.0	AMH	Manhole	10	NA
		.0	MWL	Water Level	21	NA
		36.7	TBD	Tap Break-in Defective	107	M 3
		36.7	RFC	Roots Fine Connection	118	M 1
		109.0	TF	Tap Factory	275	NA
	/	185.5	TFA	Tap Factory Active	442	NA
	$\vdash \downarrow'$	261.5	LFAC	Lining Failure Abandoned Connection	606	NA
		268.3	DAGS	Deposits Attached Grease	631	M 2
		268.3	TF	Tap Factory	643	NA
5		279.7	MGO	General Observation	678	NA
ecti		293.9	AMH	Manhole	718	NA
Camera Direction						
M(305-03	8				




Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-305-037




Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 10.000 Continuous Index: Within 8" of Joint: NO Remarks:




Code: Description:	TBD Tap Break-in Defective
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	36.7 0 3 10 4.000




Code:RFCDescription:Roots Fine Connection

Distance (ft):	36.7
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	10
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	109.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description:

Tap Factory Active Distance (ft): 185.5 Structural Grade: 0 O&M Grade: 0 9

TFA

4.000

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:

LFAC Lining Failure Abandoned Connection
261.5
0
0
9
NO



Code:DAGSDescription:Deposits Attached Grease

Distance (ft):	268.3
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	10
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	268.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	11
Clock To:	
1st Value:	6.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:MGODescription:General Observation

279.7 Distance (ft): Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: NO Remarks: **SLIGHT FOG**

Code:

Description:



Distance (ft):	293.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-305-038 PASSES MH

AMH

Manhole