Profile/Photo Observation Report



Date: **04/17/2018** Weather: Coding: **PACP 6.0**

Pipe Length (ft): 295.0 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: Surveyor: Justin Gonzales PSR: P-305-040-039

Customer: Clean Date: 01/01/1900 Shape: C

Street: FOXCROFT STREET Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Yard Tape/Media #:

Purpose: Routine Assessment Dia/Height: 10"
Use: Sanitary Material: PVC

Drain Area: NA Lining: Cured in Place

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-305-040 DS MH: M-305-039 Total Length Surveyed (ft): 293.1

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

AMH	Manhole	10	NA
MWL	Water Level	21	NA
TF	Tap Factory	164	NA
TF	Tap Factory	281	NA
LFAC	Lining Failure Abandoned Connection	333	NA
MGO	General Observation	437	NA
MGO	General Observation	450	NA
MGO	General Observation	514	NA
ТВ	Tap Break-in	536	NA
MGO	General Observation	557	NA
MGO	General Observation	581	NA
MGO	General Observation	620	NA
TF	Tap Factory	750	NA
AMH	Manhole	782	NA
	TF TF LFAC MGO MGO MGO TB MGO MGO MGO TTB MGO MGO TF	TF Tap Factory TF Tap Factory LFAC Lining Failure Abandoned Connection MGO General Observation MGO General Observation MGO General Observation TB Tap Break-in MGO General Observation MGO General Observation MGO General Observation MGO General Observation TF Tap Factory	TF Tap Factory 164 TF Tap Factory 281 LFAC Lining Failure Abandoned Connection 333 MGO General Observation 437 MGO General Observation 450 MGO General Observation 514 TB Tap Break-in 536 MGO General Observation 557 MGO General Observation 557 MGO General Observation 581 MGO General Observation 581 MGO General Observation 620 TF Tap Factory 750

Code:



Description:	Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-305-039	

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To:

1st Value: 2nd Value:

Value Percent: 5.000


Continuous Index:

Within 8" of Joint: NO

Remarks:

Code: TF

Description: **Tap Factory**




Distance (ft): 65.5 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 11

Clock To:

Remarks:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF**

Description: Tap Factory

Distance (ft): 117.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: LFAC

Description: Lining Failure Abandoned


Connection

Distance (ft): 137.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks:



Description: General Observation

Distance (ft): 182.8
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: rear camera

Code: MGO

Description: General Observation

Distance (ft): 182.8
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: CAMERA HUE PINK



Description: General Observation

Distance (ft): 206.6
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: CAMERA STATUS NORMAL



Code: TB

Description: Tap Break-in


Distance (ft): 210.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Description: General Observation


Distance (ft): 212.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: CAMERA PINK HUE



Code: MGO

Description: General Observation

Distance (ft): 216.6
Structural Grade: 0


O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: CAMERA NORMAL



Description: General Observation

Distance (ft): 228.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks: PINK HUE INTERMITENT

NO



Code: **TF**

Description: Tap Factory

Distance (ft): 285.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 293.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks: M-305-040

NO