
Profile/Ph	oto Observatio	n Report				RedZone
Date:	03/21/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft)): 356.9	Owner:	NA		Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	Selasie H	lonu	PSR:	P-308-011-010
Customer:		Clean Date	e: 01/01/1	900	Shape:	C
Street:	AMBER DR & DIA	AMBER DR & DIAMOND DR F		rol:	Not Controlled	
City:	Hobart, IN		Year Rene	wed:		
Location:	Light Highway		Tape/Med	lia #:		
Purpose:	Routine Assessme	ent	Dia/Heigh	t:	8"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:	Flow direction wr	ong				
Location Detail	s:		Direction	of Survey:	Upstream	
US MH:	M-308-010	DS MH:	M-308-011	Т	otal Length Surveyed (ft)	: 345.7
D&M Index:	0.00	O&M Quicl	k:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural (Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Qui	ick:	0000	Overall Rating:	0.00






Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-308-011



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	71.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	2
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	345.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-308-010