
Profile/Ph	oto Observation	Report				RedZone
Date:	03/21/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft): 44.3	Owner:	NA		Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	Selasie Ho	onu	PSR:	P-308-027-026
Customer:		Clean Date:	01/01/19	00	Shape:	С
Street:	FOXCROFT STREET		Flow Contro	ol:	Not Controlled	
City:	Hobart, IN		Year Renew	ved:		
Location:	Light Highway		Tape/Medi	a #:		
Purpose:	Routine Assessmen	nt	Dia/Height:	:	8"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:	Flow direction wro	ng				
Location Detail	S:		Direction o	f Survey:	Downstream	
US MH:	M-308-026	DS MH:	M-308-027	Т	otal Length Surveyed (ft)	: 46.1
D&M Index:	0.00	O&M Quick:	:	0000	O&M Rating:	0.00
Structural Index:	0.00	 Structural Q	uick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quic	:k:	0000	Overall Rating:	0.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-308-026




Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	25.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	11
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	46.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-308-027