
Profile/Ph	oto Observatio	n Report			RedZon
Date:	03/23/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft): 6.7	Owner:	NA	Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	Jen Costello	PSR:	P-308-035-031
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	OFF W 61ST AVE		Flow Control:	Not Controlle	d
City:	Hobart, IN		Year Renewed:		
Location:	Light Highway		Tape/Media #:		
Purpose:	Routine Assessme	ent	Dia/Height:	8"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:	F_S_P_C at 0 ft bu	uild up around the pi	ipe		
Location Detail	ls:		Direction of Survey:	Downstream	
US MH:	M-308-031	DS MH: M	-308-035	Total Length Surveyed (ft	:): .8
0&M Index:	3.00	O&M Quick:	3100	O&M Rating:	3.00
tructural Index:	0.00	Structural Quick	<: 0000	Structural Rating	0.00
Verall Index:	3.00	Overall Quick:	3100	Overall Rating:	3.00






Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-308-031




Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	MSA Abandoned Survey
Distance (ft):	.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	OVERTURNED

Code:DAGSDescription:Deposits Attached Grease



Distance (ft):	.8
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	20.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	