Profile/Photo Observation Report



Date: 03/29/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 240.1 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-403-001-002 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: W 38TH AVE & GILL ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-403-002 DS MH: M-403-001 Total Length Surveyed (ft): 112.4

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

	Code	Observation	Video (sec)	Grade
403-002				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
23.4	TFA	Tap Factory Active	80	NA
/40.3	TF	Tap Factory	126	NA
/ 112.4	MSA	Abandoned Survey	282	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-403-002

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

20.000

4.000

NO



Code: **TFA**

Description: **Tap Factory Active**


Distance (ft): 23.4 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 9

Clock To:

1st Value: 2nd Value:

Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 40.3
Structural Grade: 0

O&M Grade: 0


Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Description: Abandoned Survey



Distance (ft): 112.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: **DEBRIS UNDER WATER**