## **Profile/Photo Observation Report**

1.88

2.20

2.06

O&M Index:

Structural Index:

Overall Index:

O&M Quick:

Structural Quick:

Overall Quick:



15.00

22.00

37.00

Date:	10/23/2021	Weather:		Coding:	PACP 7.0
Pipe Length (ft)	: <b>88.8</b>	Owner:	City of Hobart	Pre Clean:	<b>Heavy Cleaning</b>
P.O.#:	YES502259	Surveyor:	S. Bucklin	PSR:	P-404-011-010
Customer:	City of Hobart	Clean Date:	10/22/2021	Shape:	С
Street:	North Wabash Stre	et	Flow Control:	Not Controlled	ı
City:	Hobart, IN		Year Renewed:		
Location:	Local rural streets v	with light traffic	, t Tape/Media #:		
Purpose:	Routine Assessmen	nt	Dia/Height:	8"	
Use:	Sanitary Sewage Pi	pe	Material:	VCP	
Drain Area:			Lining:	None	
Category:	NA				
Comment:					
Location Details	5:		Direction of Survey:	Upstream	
US MH:	M-404-011	DS MH:	M-404-010	Total Length Surveyed (ft	): <b>88.8</b>


3223

O&M Rating:


Structural Rating:

Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
M(404	-010				
	0.0	AMH	Manhole	1	NA
-11	0. //	MWL	Miscellaneous Water Level	45	NA
-	3.4	MMC	Miscellaneous Material Change	98	NA
ш	3.4	JOL	Joint Offset Large	117	S 4
ш	8.2	OBZ	Obstruction Other	157	M 2
ш	9.5	MMC	Miscellaneous Material Change	198	NA
ш	25.6	RMJ	Roots Medium Joint	290	M 3
- 11	35.0	MWLS(S01)	Miscellaneous Water Level Sag	349	S 2
-11	46.9	RFJ	Roots Fine Joint	431	M 1
s <del>   </del>	51.0	RMJ	Roots Medium Joint	488	M 3
Camera Direction	59.4	RFJ	Roots Fine Joint	572	M 1
	63.5	OBZ	Obstruction Other	624	M 2
	<u> </u>	IWJ	Infiltration Weeper Joint	636	M 2
Ш	73.2	MWLS(F01)	Miscellaneous Water Level Sag	699	S 2
	80.4	MWLS	Miscellaneous Water Level Sag	732	S 2
	84.1	RFJ	Roots Fine Joint	755	M 1
ļ III	88.8	AMH	Manhole	850	NA



Code: Description:	AMH Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-404-010		



Code: MWL

Description: Miscellaneous Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO



Code: MMC

Description: Miscellaneous Material Change

Distance (ft): 3.4
Structural Grade: 0


O&M Grade: 0

Clock Start/From: Clock To:

1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: VCP TO PVC



Code: JOL

Description: Joint Offset Large

Distance (ft): 3.4
Structural Grade: 4

O&M Grade: 0

Clock Start/From:

Clock To:

1st Value: **1.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: OBZ

Description: Obstruction Other

Distance (ft): 8.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 5
Clock To: 7
1st Value:


Value Percent: 5.000

Continuous Index:

2nd Value:

Within 8" of Joint: YES

Remarks: LOOKS TO BE A SEWER RODDER.



Code: MMC

Description: Miscellaneous Material Change

Distance (ft): 9.5
Structural Grade: 0


O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: PVC TO VCP



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 25.6
Structural Grade: 0

O&M Grade: 3

Clock Start/From: 2

Clock To: 6

1st Value:


Value Percent: **35.000** 

Continuous Index:

Within 8" of Joint: YES

Remarks:

2nd Value:



Code: MWLS

Description: Miscellaneous Water Level Sag

Distance (ft): 35.0 Structural Grade: 2


O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: S01
Within 8" of Joint: NO

Remarks:




Code: RFJ

Description: Roots Fine Joint

Distance (ft): 46.9
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES

Remarks:



10/23/21

Code: RMJ

Description: Roots Medium Joint

Distance (ft): 51.0
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 9
Clock To: 3

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

Code:

Description: Roots Fine Joint

YES

RFJ

Distance (ft): 59.4
Structural Grade: 0

O&M Grade: 1

Clock Start/From: 11

Clock To: 1

1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:

0.00 ft/min



Code: OBZ

Description: Obstruction Other

Distance (ft): 63.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 4
Clock To: 6

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks: LOOKS TO BE PART OF A SEWER

RODDER



Code: IWJ

Description: Infiltration Weeper Joint

Distance (ft): 63.6
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 3

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: **MWLS** 

Description: **Miscellaneous Water Level Sag** 

73.2 Distance (ft): Structural Grade: 2 0 O&M Grade:

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000 F01 Continuous Index: Within 8" of Joint: NO

Remarks:



Code: **MWLS** 

Description: **Miscellaneous Water Level Sag** 

Distance (ft): 80.4 Structural Grade: 2 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:


Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

9 Tuesday, April 25, 2023



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 84.1
Structural Grade: 0

O&M Grade: 1


Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: AMH
Description: Manhole

Distance (ft): 88.8
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-404-011