Profile/Photo Observation Report



Profile/Photo Observation Report								
Date: Pipe Length (ft	04/08/2018	Weather: Owner:	City of H	obart	Coding: Pre Clean:	PACP 6.0 No Pre-Cleaning		
P.O.#:	20-2	Surveyor:	M. Piela	cha	PSR:	M-404-013-M-504-065		
Customer:	City of Hobart	Clean Date:			Shape:	С		
Street:	Old Ridge Road		Flow Cont	rol:	Not Controlled			
City:	Hobart, IN		Year Rene	wed:				
Location:	Light Highway		Tape/Med	lia #:	DEP 20			
Purpose:	Routine Assessment		Dia/Heigh	t:	24"			
Use:	Sanitary		Material:		СР			
Drain Area:			Lining:					
Category:	NA							
Comment:								
Location Detai	ls:		Direction	of Survey:	Upstream			
US MH:	M-404-013	DS MH:	M-504-065		Total Length Surveyed (ft)	: 112.9		
O&M Index:	2.50	O&M Quick:		3121	O&M Rating:	5.00		
Structural Index:	0.00	Structural Qu	ıick:	0000	Structural Rating:	0.00		
Overall Index:	2.50	Overall Quick		3121	Overall Rating:	5.00		

Friday, October 1, 2021

Position	Code	Observation	Video (sec)	Grade
504-065				
0.	AMH	Manhole	0	NA
0.\	MWL	Water Level	8	NA
97.1	DAE	Deposits Attached Encrustation	135	M 2
112.8	OBZ	Obstacle Other	174	M 3
112.9	MSA	Abandoned Survey	275	NA



Code:	АМН
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-504-065

Friday, October 1, 2021



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0

O&M Grade: Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO

0

Remarks:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 97.1
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 1

Clock To: 4

1st Value:

2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks:

Friday, October 1, 2021



Code: OBZ

Description: Obstacle Other

Distance (ft): 112.8
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 5
Clock To: 8

1st Value: 2nd Value:

Value Percent: 20.000

Continuous Index:

Within 8" of Joint: NO
Remarks: Debris



Code: MSA

Description: Abandoned Survey

Distance (ft): 112.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: heavy debris

Friday, October 1, 2021 4