Profile/Photo Observation Report



Date: 04/16/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 298.3 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-404-017-016 Surveyor: Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: Summerlin Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Light Highway Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA
Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-404-016 DS MH: M-404-017 Total Length Surveyed (ft): 280.4

3.00 5122 9.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 3.00 5122 9.00 Overall Quick: Overall Rating: Overall Index:

Code	Observation	Video (sec)	Grade
АМН	Manhole	10	NA
MWL	Water Level	21	NA
TFA	Tap Factory Active	75	NA
TFA	Tap Factory Active	102	NA
TF	Tap Factory	171	NA
TFA	Tap Factory Active	285	NA
TFD	Tap Factory Defective	315	M 2
DAE	Deposits Attached Encrustation	326	M 2
OBZ	Obstacle Other	374	M 5
MGO	General Observation	385	NA
TFA	Tap Factory Active	454	NA
TF	Tap Factory	480	NA
TF	Tap Factory	603	NA
TFA	Tap Factory Active	630	NA
TF	Tap Factory	689	NA
TFC	Tap Factory Capped	716	NA
AMH	Manhole	767	NA
	AMH MWL TFA TFA TFA TFD DAE OBZ MGO TFA TF TF TF TFC	AMH Manhole MWL Water Level TFA Tap Factory Active TFA Tap Factory Active TF Tap Factory TFA Tap Factory Active TFD Tap Factory Defective DAE Deposits Attached Encrustation OBZ Obstacle Other MGO General Observation TFA Tap Factory Active TF Tap Factory TF Tap Factory TF Tap Factory TF Tap Factory TFA Tap Factory	AMH Manhole 10 MWL Water Level 21 TFA Tap Factory Active 75 TFA Tap Factory Active 102 TF Tap Factory Active 285 TFD Tap Factory Defective 315 DAE Deposits Attached Encrustation 326 OBZ Obstacle Other 374 MGO General Observation 385 TFA Tap Factory Active 454 TF Tap Factory Active 454 TF Tap Factory 603 TFA Tap Factory Active 630 TFA Tap Factory Active 630 TFA Tap Factory Active 630 TFA Tap Factory Active 689 TFC Tap Factory Capped 716

Code:

Description:



Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	

AMH

Manhole

Within 8" of Joint: NO Remarks: M-404-016



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:


Within 8" of Joint:

Remarks:

5.000

4.000

NO



Code: **TFA**


Description: **Tap Factory Active**

Distance (ft): 21.0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 9

Clock To:

1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TFA

Description: Tap Factory Active


Distance (ft): 28.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**


Description: Tap Factory

Distance (ft): 57.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TFA

Description: Tap Factory Active

Distance (ft): 107.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value:

4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 115.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: DAE



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 115.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 9
1st Value:

2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: OBZ

Description: Obstacle Other

Distance (ft): 132.9
Structural Grade: 0
O&M Grade: 5
Clock Start/From: 3
Clock To: 9
1st Value:
2nd Value:

Value Percent: 40.000

Continuous Index:

Within 8" of Joint: NO Remarks: MISC



Code: MGO

Description: General Observation


Distance (ft): 132.9
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks: REAR CAMERA



Code: TFA

Description: Tap Factory Active

Distance (ft): 160.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:



Code: TF

Description: **Tap Factory**


Distance (ft): 167.5 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 9

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TF


Description: **Tap Factory**

Distance (ft): 223.2 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 9

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TFA

Description: Tap Factory Active

Distance (ft): 230.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**


Description: Tap Factory

Distance (ft): 254.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TFC

Description: Tap Factory Capped

Distance (ft): 261.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3


Clock To:

1st Value:

4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 280.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-404-017