## **Profile/Photo Observation Report**



Date: 04/16/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 237.4 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-404-018-017 Surveyor: Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: W 41ST AVE & N WABASH ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: **NA** Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-404-017 DS MH: M-404-018 Total Length Surveyed (ft): 17.7

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:


Position	Code	Observation	Video (sec)	Grade
404-018				
0.	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
3.3	TF	Tap Factory	39	NA
16.7	TBA	Tap Break-in Active	78	NA
17.7	MSA	Abandoned Survey	91	NA

Code:



Description:	Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value: 2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-404-017	

**AMH** 



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO

Code: TF Description: **Tap Factory** 




Distance (ft): 3.3 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 3

Clock To:

Remarks:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TBA

Description: Tap Break-in Active

Distance (ft): 16.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value:

4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 17.7
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: camera underwater